



01761207

Schwake A-2, API 075-07181
COGCC Remediation Project #4886
East Cheyenne Gas Storage LLC
NWNE Sec 6, T-11-N, R-52-W
Logan County

March 3, 2011
Inspection #200300539



Oily soil, junk and trash at pumping unit.





Junk and trash at tank battery



Old piping at treater.



Junk and trash near former skim pit location



Oily soil at tank battery.



Oil saturated soils in treater shed.



Small areas of localized oily soil remain in west wall of water pit excavation.



Disturbed area adjacent east side of landfarm needs to be stabilized.



Disturbed area adjacent north side of landfarm needs to be stabilized.