Click here to reset form

FORM 4 Rev 12/05

TECHNICAL INFORMATION PAGE

FOR OGCC USE ONLY
Received
COGCC Rifle
5/5/2011

1. OGCC Operator Number: 016800 API Number: 05-077-09685
2. Name of Operator: Delta Petroleum Corporation OGCC Facility ID # 334433
3. Well/Facility Name: Pad 2A cuttings pit Well/Facility Number: NVEGA 22-121,
4. Location (QtrQtr, Sec, Twp, Rng, Meridian): NWSE, S21, T9S, R93W, 6th PM

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within 30 days of work completed as a "subsequent" report and must accompany Form 4, page 1.

5. **DESCRIBE PROPOSED OR COMPLETED OPERATIONS**

Cuttings from 2A pit were dewatered and sampled in accordance with Table 910-1. Analytical results indicated that concentrations of contaminants were above clean-up requirements. In accordance with policy, the cuttings were dried by mixing with clean local fill, left in place, and resampled. Analytical results indicated that concentrations of contaminants were still above clean-up requirements.
It is proposed that soils excavated from the produced water pipeline leak discovered on 6/7/2010 in Sec 23, T9S, R93W, tracking # ~~2607868~~, with elevated SAR be mixed with the cuttings pit contents and placed to abut the unstable cutslope at Pad 2A. The mixed cuttings and excavated soils would then be sampled for adherance to Table 910-1 standards and SAR policy, and covered with at least 2' of clean soil.

spill #2607359 is associated with 6/7/2010 spill