

Axelson, John

From: Axelson, John
Sent: Wednesday, June 29, 2011 9:50 AM
To: 'Brandon S. Bruns'
Cc: Brian Dodek; Randall Ferguson
Subject: RE: Ehrlich Form 27 - Project #5871
Attachments: PDC Ehrlich 24-7 Form 27 App 6-22-11.pdf

Brandon,

COGCC has assigned Project #5871 to the remediation being performed at the subject site. The associated spill report (#2522940) has been changed to closed status in COGIS with a reference to the ongoing remediation project. Please reference the remediation number in future correspondence related to the ongoing groundwater monitoring. An approved copy of the Form 27 is attached for your records.

Thank you,

John

John Axelson, P.G.
Environmental Protection Specialist, Northeast Region
Colorado Oil & Gas Conservation Commission
Phone: 303-637-7178
Cell: 303-877-9964
Fax: 303-637-7179

From: Brandon S. Bruns [<mailto:bbruns@petd.com>]
Sent: Wednesday, June 22, 2011 2:26 PM
To: Axelson, John
Cc: Brian Dodek; Randall Ferguson
Subject: Ehrlich Form 27 Submittal

Hi John:

Attached please find a Form 27 and supporting documentation for the subject site located in the SESW Section 7 – T6N – R64W. A Form 19 was submitted to the COGCC on November 30, 2010 (Spill # 2522940). Soil and groundwater were impacted from a dumphine release. Approximately 1,000 CY of impacted soil, from two excavations, and 2,964 barrels of impacted groundwater were removed from the site and transported to licensed disposal facilities. Five groundwater monitoring wells were installed in April 2011 and groundwater samples were subsequently collected. The initial groundwater analytical results indicate groundwater is compliance with CDPHE Regulation 41 Groundwater Standards. PDC will continue to monitor groundwater concentrations until four consecutive quarters of groundwater concentrations are compliant with Regulation 41 standards.

Please call if any questions. Thank you!

