

FORM  
5A

Rev  
02/08

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400153261

**COMPLETED INTERVAL REPORT**

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 66571

4. Contact Name: Joan Proulx

2. Name of Operator: OXY USA WTP LP

Phone: (970) 263.3641

3. Address: P O BOX 27757

Fax: (970) 263.3694

City: HOUSTON State: TX Zip: 77227

5. API Number 05-045-16010-00

6. County: GARFIELD

7. Well Name: CASCADE CREEK

Well Number: 697-09-54A

8. Location: QtrQtr: SWSE Section: 9 Township: 6S Range: 97W Meridian: 6

9. Field Name: GRAND VALLEY Field Code: 31290

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO

Status: PRODUCING

Treatment Date: 07/12/2010

Date of First Production this formation: 07/17/2010

Perforations Top: 7830 Bottom: 8695 No. Holes: 114 Hole size: 37/100

Provide a brief summary of the formation treatment:

Open Hole: ☐

4 stages of slickwater frac with 12,910 bbls of frac fluid and 492,975 lbs of proppant

This formation is commingled with another formation: ☐ Yes ☒ No

**Test Information:**

Date: 07/17/2010 Hours: 24 Bbls oil: 0 Mcf Gas: 1162 Bbls H2O: 495

Calculated 24 hour rate: Bbls oil: 0 Mcf Gas: 1162 Bbls H2O: 495 GOR: 0

Test Method: Flowing Casing PSI: 1400 Tubing PSI: 750 Choke Size: 20/64

Gas Disposition: SOLD Gas Type: DRY BTU Gas: 1048 API Gravity Oil: 0

Tubing Size: 2 + 3/8 Tubing Setting Depth: 8362 Tbg setting date: 03/31/2011 Packer Depth:

Reason for Non-Production:

Date formation Abandoned:  Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt

Bridge Plug Depth:  Sacks cement on top:

Comment:

Repair work was performed on the 697-09-54A well due to excess water. From 3/28/11 to 3/31/11, the well was clenaed down to 8698', a CIBP was set at 8625', and tubing was re-landed at 8362'.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Joan Proulx

Title: Regulatory Analyst Date: 4/13/2011 Email joan\_proulx@oxy.com  
:

---

**Attachment Check List**

Att Doc Num	Name

Total Attach: 0 Files

**General Comments**

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)