

**FORM  
5**Rev  
02/08**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

1634953

**DRILLING COMPLETION REPORT**

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type ☐ Final completion ☒ Preliminary completion

1. OGCC Operator Number: 96850

4. Contact Name: JENN MENDOZA

2. Name of Operator: WILLIAMS PRODUCTION RMT COMPANY LLC

Phone: (303) 260-4533

3. Address: 1001 17TH STREET - SUITE #1200

Fax: (303) 629-8285

City: DENVER State: CO Zip: 80202

5. API Number 05-103-11679-00

6. County: RIO BLANCO

7. Well Name: Federal RGU

Well Number: 344-24-198

8. Location: QtrQtr: NWNE Section: 25 Township: 1S Range: 98W Meridian: 6

Footage at surface: Distance: 227 feet Direction: FNL Distance: 1914 feet Direction: FEL

As Drilled Latitude: 39.940985 As Drilled Longitude: -108.340074

## GPS Data:

Date of Measurement: 08/16/2010 PDOP Reading: 3.2 GPS Instrument Operator's Name: JAMES SEAL

\*\* If directional footage at Top of Prod. Zone Dist.: feet. Direction: Dist.: feet. Direction:

Sec: Twp: Rng:

\*\* If directional footage at Bottom Hole Dist.: 679 feet. Direction: FSL Dist.: 661 feet. Direction: FEL

Sec: 24 Twp: 1S Rng: 98W

9. Field Name: SULPHUR CREEK

10. Field Number: 80090

11. Federal, Indian or State Lease Number: COC060733

12. Spud Date: (when the 1st bit hit the dirt) 02/25/2011 13. Date TD: 03/11/2011 14. Date Casing Set or D&amp;A: 03/12/2011

## 15. Well Classification:

☐ Dry ☐ Oil ☒ Gas/Coalbed ☐ Disposal ☐ Stratigraphic ☐ Enhanced Recovery ☐ Storage ☐ Observation

16. Total Depth MD 12960 TVD\*\* 12796 17 Plug Back Total Depth MD TVD\*\*

18. Elevations GR 6640 KB 6661

One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

## 19. List Electric Logs Run:

CBL AND RESERVOIR PERFORMANCE MONITOR (RPM)

## 20. Casing, Liner and Cement:

**CASING**

| Casing Type | Size of Hole | Size of Casing | Wt/Ft | Csg/Liner Top | Setting Depth | Sacks Cmt | Cmt Top | Cmt Bot | Status |
|-------------|--------------|----------------|-------|---------------|---------------|-----------|---------|---------|--------|
| CONDUCTOR   | 24           | 18             |       | 48            | 80            | 135       | 0       | 80      | CALC   |
| SURF        | 14+3/4       | 9+5/8          |       | 0             | 4,262         | 2,202     | 0       | 4,262   | CALC   |
| 1ST         | 7+7/8        | 4+1/2          |       | 0             | 12,951        | 1,455     |         | 12,951  | CALC   |

**ADDITIONAL CEMENT**

Cement work date: \_\_\_\_\_

Details of work:

| Method used | String | Cementing tool setting/pref depth | Cement volume | Cement top | Cement bottom |
|-------------|--------|-----------------------------------|---------------|------------|---------------|
|             |        |                                   |               |            |               |

21. Formation log intervals and test zones:

**FORMATION LOG INTERVALS AND TEST ZONES**

| FORMATION NAME | Measured Depth |        | Check if applies         |                          | COMMENTS (All DST and Core Analyses must be submitted to COGCC) |
|----------------|----------------|--------|--------------------------|--------------------------|---|
|                | Top            | Bottom | DST                      | Cored                    |   |
| MESAVERDE      | 8,071          |        | <input type="checkbox"/> | <input type="checkbox"/> |   |
| CAMEO          | 11,381         |        | <input type="checkbox"/> | <input type="checkbox"/> |   |
| ROLLINS        | 11,761         |        | <input type="checkbox"/> | <input type="checkbox"/> |   |
| COZZETTE       | 11,896         |        | <input type="checkbox"/> | <input type="checkbox"/> |   |
| CORCORAN       | 12,111         |        | <input type="checkbox"/> | <input type="checkbox"/> |   |
| SEGO           | 12,731         |        | <input type="checkbox"/> | <input type="checkbox"/> |   |

Comment:

SURFACE PRESSURE = 0#

LOGS WILL BE SUBMITTED TO THE COGCC BY THE SERVICE COMPANY UPON PAD DRILLOUT. WILLIAMS WILL UPLOAD DIGITAL LOGS TO THE COGCC WEBSITE. WAITING ON COMPLETIONS.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_

Print Name: JENN MENDOZA

Title: PERMIT TECH

Date: 3/23/2011

Email: JENN.MENDOZA@WILLIAMS.COM

**Attachment Check List**

| Att Doc Num                 | Document Name         | attached ? |                          |    |                                     |
|-----------------------------|-----------------------|------------|--------------------------|----|-------------------------------------|
| <u>Attachment Checklist</u> |                       |            |                          |    |                                     |
|                             | CMT Summary *         | Yes        | <input type="checkbox"/> | No | <input checked="" type="checkbox"/> |
|                             | Core Analysis         | Yes        | <input type="checkbox"/> | No | <input checked="" type="checkbox"/> |
|                             | Directional Survey ** | Yes        | <input type="checkbox"/> | No | <input checked="" type="checkbox"/> |
|                             | DST Analysis          | Yes        | <input type="checkbox"/> | No | <input checked="" type="checkbox"/> |
|                             | Logs                  | Yes        | <input type="checkbox"/> | No | <input checked="" type="checkbox"/> |
|                             | Other                 | Yes        | <input type="checkbox"/> | No | <input checked="" type="checkbox"/> |

**General Comments**

| <b><u>User Group</u></b> | <b><u>Comment</u></b>  | <b><u>Comment Date</u></b> |
|--------------------------|--|----------------------------|
| Engineer                 | Preliminary Form 5, no CBL yet.  | 3/5/2011 8:03:37 AM        |
| Permit                   | Last line of directional survey is missing. Request revision for Final Form 5. NKP | 3/2/2011 4:06:26 PM        |

Total: 2 comment(s)