

COGIS - Field Inspection Report

API Number: 05-121-10964	Name: YOUNG #33-27350
Location: NWSE 27 3S 50W	Lat: 39.76349 Long: -102.96058
Operator #:	Operator Name: CORAL PRODUCTION CORP
Inspection Date: 9/13/2011	Inspector: JOHN AXELSON

Inspection was: **Satisfactory**

Insp. Type: **ES** Insp. Stat: **PR** Reclamation (Pass, Interim or Fail): **P&A (Pass/Fail):**
 Brhd. Pressure: Inj. Pressure: T-C Ann. Pressure: UIC Violation Type:
 Violation: **N** NOAV Sent: **N** Date Corrective Action Due: Date Remedied:

Field Inspection Comments and Observations

Insp. Comment	Inspection/Violation Comments
ACTION	NONE
FIREWALL	BERMS IN FAIR CONDITION.
GENHOUSE	GOOD - WEEDS RECENTLY MOWED IN FORMER RESERVE PIT AREA.
MISC	SAMPLING ON LEASE ROAD PERFORMED AS PART OF CORRECTIVE ACTIONS RELATED TO NOAV #200308970 FOR THE CHRISTIANSEN TANK BATTERY. FLAGGED SAMPLE LOCATIONS ALONG THE LEASE ROAD WERE OBSERVED DURING THE INSPECTION.
SPILCOM	OILY DIRT AT TURN-AROUND ADJACENT TO TANK BATTERY HAS BEEN REMOVED. SAMPLE RESULTS SUBMITTED ON 9/9/11 INDITICATE NO RESIDUAL TPH OR BTEX ABOVE TABLE 910-1 STANDARDS ON LEASE ROAD.
TANKBAT	2: 300 BBL STEEL TANKS; 1: 400 BBL PRODUCED WATER TANK; PROPANE TANK; PUMPING UNIT