

Figure 1 Lithology Key

Figure 2 Stratigraphic Column

Figure 3 Composite Log

Figure 4 Core Photo

Figure 5 Core Photo

Figure 6 Core Photo

Figure 7 Core Photo

Figure 8 Core Photo

Figure 9 Core Photo

Figure 10 Core Photo

Figure 11 Core Photo

Figure 12 Core Photo

Figure 13 Core Photo

Figure



Calibration Report

Database File: c:\slowlet\servus001.DR.db
Dataset Pathname: pass1
Dataset Creation: Thu Sep 16 12:59:52 2010 by Log Bird Cassedhole SX081

Gamma Ray Calibration Report

Serial Number	
Tool Model	tempSX
Performed	Wed Sep 01 07:34:11 2010
Calibrator Value	1.0 GAPI
Background Reading	0.0 cps
Calibrator Reading	1.0 cps
Sensitivity	1.0000 GAPI/cps

CBL Calibration Report

Serial Number	111
Tool Model	TMSLOG3
Performed	Thu Sep 16 12:42:15 2010
Depth	300.250 ft
Casing Diameter	4.500 in

3 Spacing

Signal Zero	1.330	1.330 mV
Calibrated Amplitude	87.106	87.106 mV
Reading in Free Pipe	2.660	2.660 V
Reading in Free Pipe	2.464	2.500 V

5' Spacing

Gain	91.405	91.826
Offset	1.376	1.375