

SCHLUMBERGER CARBON SERVICES

SITE PHOTOS

RMCCS State No. 1 Well
SECTION 34, T6N, R91W, 6th P.M.
210' FSL 2416' FEL

DATE: 08-23-11
Drawn By: LD



Photo: View from Location Stake to North

Camera Angle: North



Photo: View from Location Stake to East

Camera Angle: East

LOCATION PHOTOS



EPP & ASSOCIATES, INC.
PROFESSIONAL LAND SURVEYORS
433 4th Avenue West
P.O. Box 837
Craig, CO 81625
Phone (970) 824-8236
Fax (970) 824-5227

SCHLUMBERGER CARBON SERVICES

SITE PHOTOS

RMCCS State No. 1 Well
SECTION 34, T6N, R91W, 6th P.M.
210' FSL 2416' FEL

DATE: 08-23-11
Drawn By: LD




Photo: View from Location Stake to South

Camera Angle: South



Photo: View from Location Stake to West

Camera Angle: West

LOCATION PHOTOS



EPP & ASSOCIATES, INC.
PROFESSIONAL LAND SURVEYORS
433 4th Avenue West
P.O. Box 837
Craig, CO 81625
Phone (970) 824-8236
Fax (970) 824-5227