

**FORM  
5**Rev  
02/08**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

2517746

**DRILLING COMPLETION REPORT**

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type ☒ Final completion ☐ Preliminary completion

1. OGCC Operator Number: 10232

4. Contact Name: RANDY NATVIG

2. Name of Operator: LARAMIE ENERGY II, LLC

Phone: (303) 339-4400

3. Address: 1512 LARIMER ST STE 1000

Fax: (303) 339-4399

City: DENVER State: CO Zip: 80202

5. API Number 05-077-10091-00

6. County: MESA

7. Well Name: BRUTON

Well Number: 19-10C

8. Location: QtrQtr: SESW Section: 19 Township: 9S Range: 93W Meridian: 6

Footage at surface: Distance: 866 feet Direction: FSL Distance: 1754 feet Direction: FWL

As Drilled Latitude: 39.257760 As Drilled Longitude: -107.814600

## GPS Data:

Date of Measurement: 05/09/2011 PDOP Reading: 2.6 GPS Instrument Operator's Name: DAVE MURREY

\*\* If directional footage at Top of Prod. Zone Dist.: 1820 feet. Direction: FSL Dist.: 1934 feet. Direction: FEL

Sec: 19 Twp: 9S Rng: 93W

\*\* If directional footage at Bottom Hole Dist.: 1804 feet. Direction: FSL Dist.: 1950 feet. Direction: FEL

Sec: 19 Twp: 9S Rng: 93W

9. Field Name: WILDCAT

10. Field Number: 99999

11. Federal, Indian or State Lease Number:

12. Spud Date: (when the 1st bit hit the dirt) 02/24/2011 13. Date TD: 03/04/2011 14. Date Casing Set or D&amp;A: 03/06/2011

## 15. Well Classification:

☐ Dry ☐ Oil ☒ Gas/Coalbed ☐ Disposal ☐ Stratigraphic ☐ Enhanced Recovery ☐ Storage ☐ Observation

16. Total Depth MD 7925 TVD\*\* 7575 17 Plug Back Total Depth MD 7868 TVD\*\* 7818

18. Elevations GR 7345 KB 7366

One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

## 19. List Electric Logs Run:

RMTE, CBL

## 20. Casing, Liner and Cement:

**CASING**

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	26	16		0	40	4	0	40	CALC
SURF	14+3/4	8+5/8		0	1,548	420	0	1,548	CALC
1ST	7+7/8	4+1/2		0	7,916	943	1,280	7,916	CBL

**STAGE/TOP OUT/REMEDIAL CEMENT**

Cement work date: \_\_\_\_\_

Method used	String	Cementing tool setting/pref depth	Cement volume	Cement top	Cement bottom

Details of work:

21. Formation log intervals and test zones:

**FORMATION LOG INTERVALS AND TEST ZONES**

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
WILLIAMS FORK	4,774		<input type="checkbox"/>	<input type="checkbox"/>	
CAMEO	7,392		<input type="checkbox"/>	<input type="checkbox"/>	
ROLLINS	7,753		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: RANDY NATVIG

Title: DRILLING MANAGER Date: 8/30/2011 Email: RNATVIG@LARAMIE-ENERGY.COM

**Attachment Check List**

Att Doc Num	Document Name	attached ?			
<u>Attachment Checklist</u>					
	CMT Summary *	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Core Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Directional Survey **	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	DST Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Logs	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Other	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
<u>Other Attachments</u>					
2517746	FORM 5 SUBMITTED	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>

**General Comments**

User Group	Comment	Comment Date
Permit	Cement summary, directional survey and well bore diagram received, being scanned.	9/28/2011 12:56:20 PM

Total: 1 comment(s)