

Inspector Name: LEONARD, MIKE

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

09/26/2011

Document Number:

664000025

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	API Number	Facility ID	Loc ID	Tracking Type
	039-06509	209604	322185	
Facility Name: RUNNING CREEK RANCH-66S64W		Inspector Name: LEONARD, MIKE		

**Operator Information:**

OGCC Operator Number: 10292	Name of Operator: THREE FORKS RESOURCES LLC
Address: 1515 WAZEE STREET - SUITE #350	
City: DENVER	State: CO Zip: 80202

**Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Irene		irene@3forksres.com	

**Compliance Summary:**

QtrQtr: SENW	Sec: 15	Twp: 6S	Range: 64W
--------------	---------	---------	------------

**Inspector Comment:**

ADDRESS LABELING ON TREATER AND WATER TANK

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num
209604	WELL	PR	09/01/2008	OW	039-06509

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

<b>Signs/Marker:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Unsatisfactory	HEATER TREATER NEEDS LABELS. WATER TANK NEEDS NFPA 704	INSTALL LABELS ON HEATER TREATER AND PRODUCED WATER TANK	12/30/2011
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Spills:</b>					
Type	Area	Volume	Corrective action	CA Date	
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing:</b>					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	
TANK BATTERY	Satisfactory	BARBED WIRE			
WELLHEAD	Satisfactory	STEEL PANELS			
<b>Equipment:</b>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Bird Protectors		Satisfactory			
Gas Meter Run	1	Satisfactory			
Horizontal Heater Treater	1	Satisfactory		BATTERY SHARED PAD WITH 15-3 AND 15-5	
Plunger Lift		Satisfactory			
<b>Tanks/Berms:</b> <input type="checkbox"/> New Tank    Tank ID: _____					
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS	,	
S/U/V:		Comment:	WATER TANK IS SHAREED WITH 15-3 AND 15-5 AT SHARED BATTERY PAD ON 15-5 PAD		
Corrective Action:				Corrective Date:	
<b>Paint</b>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	Comment
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Corrective Action				Corrective Date	

<b>Tanks/Berms:</b>		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST	39.529120,-104.548430	
S/U/V:			Comment:		
Corrective Action:					Corrective Date:
<b>Paint</b>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	Comment
Corrective Action					Corrective Date
<b>Venting:</b>					
Yes/No	Comment				
<b>Flaring:</b>					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	



DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS File: \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? PassProduction areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_**RESTORATION AND REVEGETATION**CroplandTop soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established PassNon-CroplandTop soil replaced Pass Recontoured \_\_\_\_\_ 80% Revegetation Pass

1003 f. Weeds Noxious weeds? \_\_\_\_\_ P \_\_\_\_\_

Comment: \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____		Date Final Reclamation Completed: _____	
Final Land Use: _____			
Reminder: _____			
Comment: <div></div>			
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____		
Debris removed _____	No disturbance /Location never built _____		
Access Roads _____	Regraded _____	Contoured _____	Culverts removed _____
Gravel removed _____			
Location and associated production facilities reclaimed _____		Locations, facilities, roads, recontoured _____	
Compaction alleviation _____		Dust and erosion control _____	
Non cropland: Revegetated 80% _____		Cropland: perennial forage _____	
Weeds present _____	Subsidence _____		
Comment: <div></div>			
Corrective Action: <div></div>			Date _____

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
S/U/V: _____ Corrective Date: _____ Comment: _____ CA: _____						

Comment	User	Date
ADDRESS LABELING ON TREATER AND WATER TANK	leonardm	10/24/2011