

Inspector Name: QUINT, CRAIG

FORM
INSPRev
05/11

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

11/04/2011

Document Number:

663900048

Overall Inspection:

Satisfactory

FIELD INSPECTION FORM

Location Identifier	API Number	Facility ID	Loc ID	Tracking Type
	073-06439	420575	420576	
Facility Name: Mahalo # 2			Inspector Name: QUINT, CRAIG	

Operator Information:

OGCC Operator Number:	96340	Name of Operator:	WIEPKING-FULLERTON ENERGY LLC
Address:	4600 S DOWNING ST		
City:	ENGLEWOOD	State:	CO
Zip:	80113		

Contact Information:

Contact Name	Phone	Email	Comment
Halde, Kerry	719-346-0653 off	haldesand@centurytel.net	719-340-0329 cell

Compliance Summary:

QtrQtr:	NENW	Sec:	29	Twp:	10S	Range:	55W
---------	------	------	----	------	-----	--------	-----

Inspector Comment:

CENTRAL BATTERY 1300' WEST @ MAHALO #1

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num
420575	WELL	XX	11/27/2010		073-06439

Equipment:Location Inventory

Special Purpose Pits:	Drilling Pits:	1	Wells:	1	Production Pits:
Condensate Tanks:	Water Tanks:		Separators:		Electric Motors:
Gas or Diesel Mortors:	Cavity Pumps:		LACT Unit:		Pump Jacks:
Electric Generators:	Gas Pipeline:		Oil Pipeline:	1	Water Pipeline:
Gas Compressors:	VOC Combustor:		Oil Tanks:		Dehydrator Units:
Multi-Well Pits:	Pigging Station:		Flare:		Fuel Tanks:

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
ADEQ	Satisfactory	DIRT ROAD		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	(NEW WELL, SIGN ON ORDER)NO VISIBLE WELL SIGN	INSTALL WELL SIGN A.S.A.P.	02/04/2012

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Inspector Name: QUINT, CRAIG

Comment:	
Corrective Action:	

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory	LOCATION FENCED WITH WIRE		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ancillary equipment	2	Satisfactory	PROPANE TANK, GAS SCRUBBER		
Prime Mover	1	Satisfactory	GAS ENGINE, M&M HD800A-6A		
Pump Jack	1	Satisfactory	LUFIN 456D		
Deadman # & Marked	4	Satisfactory			

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 420576

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	koepsear	Ready to pass 11/24/2010.	11/04/2010
Permit	vigilj	PERMITTING PASSED- JLV	11/05/2010

Wildlife BMPs:**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 420575

API Number: 073-06439

Status: XX

Insp. Status: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Inspector Name: QUINT, CRAIG

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____

Owner Name: _____

GPS File: _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? Pass CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail

Production areas have been stabilized? Pass

Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass

Recontoured Pass

80% Revegetation Fail

1003 f. Weeds Noxious weeds? P

Inspector Name: QUINT, CRAIG

Comment: PITS HAVE BEEN BACK FILLED, LOCATION CONTOURED AND READY TO SEED. CONTINUE WITH INTERIM RECAMATION.

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads _____

Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
------------------	-----------------	-------------------------	-----------------------	---------------	--------------------------	---------