

FORM INSP Rev 05/11	State of Colorado				DE	ET	OE	ES
	Oil and Gas Conservation Commission				Inspection Date: <u>10/27/2011</u>			

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>LABOWSKIE, STEVE</u>
	<u>214256</u>	<u>312080</u>		

Document Number:
661700003

Overall Inspection:
Satisfactory

Operator Information:

OGCC Operator Number: 96705 Name of Operator: WILLIAMS PRODUCTION COMPANY LLC

Address: P O BOX 3102 MS-25-2

City: TULSA State: OK Zip: 74101

Contact Information:

Contact Name	Phone	Email	Comment
VandenBerg, Randy		randyn.vandenbergh@williams.com	
Lane, Myke		myke.lane@williams.com	

Compliance Summary:

QtrQtr: SWNW Sec: 14 Twp: 33N Range: 10W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
10/11/1994	500147075	BH	PR			P	N
10/06/2000	200011057	PR	PR	S		P	N
05/11/2004	200057811	PR	PR	S		P	N
11/20/2001	200022020	PR	PR	S		P	N
05/30/1995	500147076	BH	PR				N
11/24/1997	500147078	PR	PR			P	N
12/27/2010	200290234	PR	PR	S			N
09/21/1994	500147074	PR	PR			P	N
11/15/2005	200085443	PR	PR	S		P	N
02/02/1996	500147077	PR	PR			P	N
10/06/2000	200011059	PR	PR	S		P	N
03/17/2009	200206053	PR	PR	S			N
09/23/2003	200045256	PR	PR	S		P	N
05/12/1998	500147079	BH	PR			P	N
07/01/1999	500147080	PR	PR			P	N
03/06/2007	200108224	PR	PR	S		P	N

Inspector Comment:

not required, but some wellhead barriers or fencing would be beneficial at this location.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
214256	WELL	PR	12/22/2006	GW	067-05590	BONDAD 33-10 20	<input checked="" type="checkbox"/>

Equipment:		<u>Location Inventory</u>	
Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	sign reads Boandad 33-10 #20-14, database reads Bondad 33-10 #20		
TANK LABELS/PLACARDS	Unsatisfactory		label tank	01/02/2012

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK BATTERY	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Horizontal Heated Separator	1				
Gas Meter Run	1				

Tanks/Berms:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	OTHER	PBV STEEL	,	
S/U/V:	Unsatisfactory	Comment:			
Corrective Action: label tank with contents, capacity and appropriate NFPA placard				Corrective Date: 01/07/2012	
Paint					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	Comment
Corrective Action				Corrective Date	
Venting:					
Yes/No		Comment			
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 312080

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Wildlife BMPs:

Stormwater:

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Data retrieval failed for the subreport, 'rptInsp11',

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS File: _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____
Comment: _____

- 1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
- Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
- Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
- Guy line anchors removed? Pass CM _____
CA _____ CA Date _____
- Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? Pass
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

- 1003 f. Weeds Noxious weeds? _____
Comment: _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____
Final Land Use: _____

Reminder:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
------------------	-----------------	-------------------------	-----------------------	---------------	--------------------------	---------

--	--	--	--	--	--	--