



Unpermitted pit
Erin 21-15

11.28.2011 16:36

A photograph of a dry, eroded hillside. The foreground and middle ground show exposed soil and rocks, with sparse, dry grass and small shrubs. A road is visible in the background, winding through a valley. The text "Lack of erosion controls" is overlaid in white, followed by "Erin 21-15 and 21-15 TR" and "location" on the next line.

Lack of erosion controls
Erin 21-15 and 21-15 TR
location

11.28.2011 16:41