

FORM
5

Rev
02/08

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:
2285197

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type Final completion Preliminary completion

1. OGCC Operator Number: 100185
2. Name of Operator: ENCANA OIL & GAS (USA) INC
3. Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-
4. Contact Name: SHEILLA REED-HIGH
Phone: (720) 876-3678
Fax: (720) 876-4678

5. API Number 05-123-31748-00
6. County: WELD
7. Well Name: PURITAN Well Number: 4-4-34
8. Location: QtrQtr: NWSE Section: 34 Township: 2N Range: 68W Meridian: 6
Footage at surface: Distance: 2017 feet Direction: FSL Distance: 2093 feet Direction: FEL
As Drilled Latitude: As Drilled Longitude:

GPS Data:

Data of Measurement: PDOP Reading: GPS Instrument Operator's Name:

** If directional footage at Top of Prod. Zone Dist.: 2574 feet. Direction: FSL Dist.: 2607 feet. Direction: FEL

Sec: 34 Twp: 2N Rng: 68W

** If directional footage at Bottom Hole Dist.: 2575 feet. Direction: FSL Dist.: 2616 feet. Direction: FEL

Sec: 34 Twp: 2N Rng: 68W

9. Field Name: SPINDLE 10. Field Number: 77900

11. Federal, Indian or State Lease Number:

12. Spud Date: (when the 1st bit hit the dirt) 07/30/2011 13. Date TD: 08/03/2011 14. Date Casing Set or D&A: 08/04/2011

15. Well Classification:

Dry Oil Gas/Coalbed Disposal Stratigraphic Enhanced Recovery Storage Observation

16. Total Depth MD 8343 TVD** 8273 17 Plug Back Total Depth MD 8282 TVD** 8212

18. Elevations GR 5002 KB 5015

One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:

CBL, DUAL IND/COMPENSATED DENSITY/COMPENSATED NEUTRON

20. Casing, Liner and Cement:

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
SURF	12+1/4	8+5/8		0	854	370	0	854	CALC
1ST	7+7/8	4+1/2		0	8,329	670	3,750	8,329	CBL

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____

Method used	String	Cementing tool setting/pref depth	Cement volume	Cement top	Cement bottom

Details of work:

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES					
FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
SUSSEX	4,629		<input type="checkbox"/>	<input type="checkbox"/>	
NIOBRARA	7,459		<input type="checkbox"/>	<input type="checkbox"/>	
CODELL	7,762		<input type="checkbox"/>	<input type="checkbox"/>	
J SAND	8,200		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: SHEILLA REED-HIGH

Title: OPERATIONS Date: 9/28/2011 Email: SHEILLA.REEDHIGH@ENCANA.COM

Attachment Check List

Att Doc Num	Document Name	attached ?	
<u>Attachment Checklist</u>			
2285199	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
2072818	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
<u>Other Attachments</u>			
2285197	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

General Comments

User Group	Comment	Comment Date
Permit	REC D/S AND PROCESSED	11/21/2011 11:20:51 AM
Permit	REQ D/S, AS DRILLED AND MWD/FMI LOGS, D/S ATTACHED IS FOR WRONG WELL, REMOVED IT	11/21/2011 10:03:28 AM
Data Entry	CHECK DIRECTIONAL FOOTAGE TOP ZONE AND BOTTOM HOLE.	11/18/2011 10:27:10 AM

Total: 3 comment(s)