

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

01/18/2012

Document Number:

663900397

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>208548</u>	<u>381181</u>		<u>QUINT, CRAIG</u>

**Operator Information:**OGCC Operator Number: 19170 Name of Operator: CONQUEST OIL COMPANYAddress: 8207 W 20TH STREET - SUITE BCity: GREELEY State: CO Zip: 80634**Contact Information:**

Contact Name	Phone	Email	Comment
	<u>970-356-5560</u>	<u>rae@cconquestcompanies.com</u>	

**Compliance Summary:**QtrQtr: SESW Sec: 7 Twp: 12S Range: 50W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/03/2010	200269753	PR	WO	U			Y
09/18/1996	500140859	SR	DA		P	P	N
07/21/1995	500140858	DG	ND			P	N

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
208548	WELL	PR	11/08/2010	DA	017-07483	HOUSE 24-7 #1	<input checked="" type="checkbox"/>

**Equipment:****Location Inventory**

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>1</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>1</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: <u>1</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	PARTIALLY SAND AND GRAVEL ROAD THROUGH PASTURE WITH 2 CATTLE GUARDS.		

<b>Signs/Marker:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	NO VISIBLE WELL SIGN	Install sign to comply with rule 210.b.	04/18/2012
TANK LABELS/PLACARDS	Unsatisfactory	NO TANK LABELING	Install sign to comply with rule 210.b.	04/18/2012

Emergency Contact Number: (S/U/V) Unsatisfactory Corrective Date: 04/18/2012

Comment: NO EMERGENCY CONTACT NUMBERS

Corrective Action: INSTALL EMERGENCY CONTACT NUMBERS

<b>Good Housekeeping:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	Unsatisfactory	CASING AND RODS BY WELLHEAD AND SPOIL PILE	REMOVE UNUSED EQUIPMENT	04/19/2012

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
Crude Oil	WELLHEAD	<= 5 bbls	SMALL AMOUNT OF OIL BY WELLHEAD FROM STUFFING BOX LEAK NEEDS REMOVED AND REMEDIATED.	04/19/2012

☐ Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory	LOCATION FENCED WITH WIRE		

<b>Equipment:</b>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Prime Mover	1	Satisfactory	EA-30 AJAX GAS ENGINE		
Ancillary equipment		Unsatisfactory	PROPANE TANK, DAY TANK, 2 -CHEMICAL TANKS WITHOUT CONTAINMENTS	INSTALL CONTAINMENTS	04/18/2012
Pump Jack	1	Satisfactory	228 SMACO		

Inspector Name: QUINT, CRAIG

<b>Tanks/Berms:</b> <input type="checkbox"/> New Tank    Tank ID: _____				
Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST	39.012180,-103.043480
S/U/V:	Satisfactory		Comment: LIGHT GRAY WITH RUST STAINING	
Corrective Action:				Corrective Date:
<b>Paint</b>				
Condition	Adequate			
Other (Content) _____				
Other (Capacity) _____				
Other (Type) _____				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				
<b>Venting:</b>				
Yes/No		Comment		
NO				
<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID:    381181

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**Wildlife BMPs:**

BMP Type	Comment
PROPOSED BMPs	<p>Proposed BMP Plan</p>       <p>Conquest Oil Company</p> <p>8207 West 20th Street</p> <p>Greeley, CO 80634</p> <p>c/o Ted Pagano</p> <p>970 -590 -3944 (Cell)</p> <p>303 -595 -1530 (Fax)</p>       <p>Stormwater Discharges Associated with Construction Oil and Gas Activity. Application has been</p>

filed with Colorado Department of Public Health and Environment Water Quality Control Division and is pending. Approved permit will be in place before any dirt work begins.

Re -Enter House 24 -7 # 1 well

T12S, R50W

Sec. 7: SE1/4SW1/4

Cheyenne County, Colorado

Description of Well Site and Construction Area

1 -3 acre site with access road for drilling of oil and gas well. Terrain is flat to rolling with native grass and sagebrush. No receiving waters will be affected by well pad. Drilling pits closed and reclaimed with the drillsite, reseeded within 6 months weather permitting. Silt fences will be installed on low side site of drill site. Topsoil will be separated and spread on drill site as final operation before reseeding operations. To prevent soil erosion site will be disked and straw crimped in.

Stormwater Management Plan (SWMP) is on file in Conquest Oil Company office.

Spill Prevention, Control and Countermeasure Plan is on file in Conquest Oil Company office.

Physical Address: 401 Arapahoe St.

id Mail to: Box 384 Kiowa, CO 80117

F; - n Sure CO. Ph. 303 -621 -8672 - Fax 303 -621 -2717

[www.highprairiesurvey.com](http://www.highprairiesurvey.com)

Job # 10026 -HOUSE 24 -7 #1 Inv # 1085

High Prairie Surveying of Kiowa, Colorado has in accordance with a request from Jack Fincham, Conquest Oil Company has determined the location of House 24 -7 #1 (a capped well casing) to be 900 feet FSL, and 2204 feet FWL, (90° off Section lines) of SECTION 7, Township 12s, Range 50w of the 6th Principal Meridian, Cheyenne County, Colorado.

Date: Staked on 2/25/2010 drawn on 3/1/2010. Re: Staked by Keith Westfall

Drawn: Drawn by Elijah Frane Topo Exhibit

**Stormwater:**

**Comment:**

**Staking:**

Inspector Name: QUINT, CRAIG

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Well**

Facility ID: 208548

API Number: 017-07483

Status: PR

Insp. Status: PR

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Fail CM \_\_\_\_\_ RODS AND CASINGCA REMOVE UNUSED EQUIPMENT CA Date **04/18/2012**Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? FailProduction areas have been stabilized? Pass Segregated soils have been replaced? Fail**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-CroplandTop soil replaced Fail Recontoured Fail 80% Revegetation Fail1003 f. Weeds Noxious weeds? P

Comment: UNUSED AREAS OF THE LOCATION HAVE BEEN PARTIALLY CONTOURED WITH A SPOIL PILE PRESENT. NO EVIDENCE OF SEEDING.

Overall Interim Reclamation Fail**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: QUINT, CRAIG

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	MHSP	Fail	

S/U/V: Unsatisfactory Corrective Date: 04/18/2012

Comment: 2-CHEMICAL TANKS WITHOUT CONTAINMENTS

CA: INSTALL CONTAINMENTS.