

FORM  
5A

Rev  
02/08

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400248531

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 100185  
2. Name of Operator: ENCANA OIL & GAS (USA) INC  
3. Address: 370 17TH ST STE 1700  
City: DENVER State: CO Zip: 80202-  
4. Contact Name: Sheilla Reed-High  
Phone: (720) 876-3678  
Fax: (720) 876-4678

5. API Number 05-123-33507-00  
6. County: WELD  
7. Well Name: ARISTOCRAT ANGUS  
Well Number: 6-8-3  
8. Location: QtrQtr: NESE Section: 3 Township: 3N Range: 65W Meridian: 6  
9. Field Name: WATTENBERG Field Code: 90750

Completed Interval

FORMATION: CODELL Status: COMMINGLED

Treatment Date: 11/11/2011 Date of First Production this formation: 11/25/2011  
Perforations Top: 7261 Bottom: 7278 No. Holes: 34 Hole size: 0.42

Provide a brief summary of the formation treatment: Open Hole: ☐

Frac'd the Codell 7261' - 7278', (34 holes) w/ 88,326 gal 22 # Vistar Hybrid cross linked gel containing 251,000 # 20/40 sand. 11-11-11

This formation is commingled with another formation: ☒ Yes ☐ No

Test Information:

Date: Hours: Bbls oil: Mcf Gas: Bbls H2O:  
Calculated 24 hour rate: Bbls oil: Mcf Gas: Bbls H2O: GOR:  
Test Method: Casing PSI: Tubing PSI: Choke Size:  
Gas Disposition: Gas Type: BTU Gas: API Gravity Oil:  
Tubing Size: Tubing Setting Depth: Tbg setting date: Packer Depth:

Reason for Non-Production:

Date formation Abandoned: Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt

Bridge Plug Depth: Sacks cement on top:

FORMATION: J SAND Status: PRODUCING

Treatment Date: 11/11/2011 Date of First Production this formation: 11/25/2011

Perforations Top: 7737 Bottom: 7779 No. Holes: 48 Hole size: 0.42

Provide a brief summary of the formation treatment: \_\_\_\_\_ Open Hole: ☐

Frac'd the J-Sand 7737'– 7779', (48 holes) w/ 60,606 gal 18 # Vistar Hybrid cross linked gel containing 250,940# 20/40 Sand. 11-11-11

This formation is commingled with another formation: ☒ Yes ☐ No

**Test Information:**

Date: \_\_\_\_\_ Hours: \_\_\_\_\_ Bbls oil: \_\_\_\_\_ Mcf Gas: \_\_\_\_\_ Bbls H2O: \_\_\_\_\_

Calculated 24 hour rate: \_\_\_\_\_ Bbls oil: \_\_\_\_\_ Mcf Gas: \_\_\_\_\_ Bbls H2O: \_\_\_\_\_ GOR: \_\_\_\_\_

Test Method: \_\_\_\_\_ Casing PSI: \_\_\_\_\_ Tubing PSI: \_\_\_\_\_ Choke Size: \_\_\_\_\_

Gas Disposition: \_\_\_\_\_ Gas Type: \_\_\_\_\_ BTU Gas: \_\_\_\_\_ API Gravity Oil: \_\_\_\_\_

Tubing Size: \_\_\_\_\_ Tubing Setting Depth: \_\_\_\_\_ Tbg setting date: \_\_\_\_\_ Packer Depth: \_\_\_\_\_

Reason for Non-Production: \_\_\_\_\_

Date formation Abandoned: \_\_\_\_\_ Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt \_\_\_\_\_

Bridge Plug Depth: 7330 Sacks cement on top: \_\_\_\_\_

FORMATION: NIOBRARA-CODELL Status: PRODUCING

Treatment Date: 11/11/2011 Date of First Production this formation: 11/25/2011

Perforations Top: 6992 Bottom: 7278 No. Holes: 126 Hole size: 0.42

Provide a brief summary of the formation treatment: \_\_\_\_\_ Open Hole: ☐

This formation is commingled with another formation: ☒ Yes ☐ No

**Test Information:**

Date: \_\_\_\_\_ Hours: \_\_\_\_\_ Bbls oil: \_\_\_\_\_ Mcf Gas: \_\_\_\_\_ Bbls H2O: \_\_\_\_\_

Calculated 24 hour rate: \_\_\_\_\_ Bbls oil: \_\_\_\_\_ Mcf Gas: \_\_\_\_\_ Bbls H2O: \_\_\_\_\_ GOR: \_\_\_\_\_

Test Method: \_\_\_\_\_ Casing PSI: \_\_\_\_\_ Tubing PSI: \_\_\_\_\_ Choke Size: \_\_\_\_\_

Gas Disposition: \_\_\_\_\_ Gas Type: \_\_\_\_\_ BTU Gas: \_\_\_\_\_ API Gravity Oil: \_\_\_\_\_

Tubing Size: \_\_\_\_\_ Tubing Setting Depth: \_\_\_\_\_ Tbg setting date: \_\_\_\_\_ Packer Depth: \_\_\_\_\_

Reason for Non-Production: \_\_\_\_\_

Date formation Abandoned: \_\_\_\_\_ Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt \_\_\_\_\_

Bridge Plug Depth: \_\_\_\_\_ Sacks cement on top: \_\_\_\_\_

