

The Road to Excellence Starts with Safety

Sold To #: 304535	Ship To #: 2285832	Quote #:	Sales Order #: 9201364
Customer: PDC ENERGY EBUS	Well Name: National Hog Farm	Customer Rep: ALVARODO, PHILIP	
Field: Wattenberg	City (SAP): GREELEY	Well #: 13-9	API/UWI #:
Legal Description:	County/Parish: Weld	State: Colorado	
Lat: N 40.412 deg. OR N 40 deg. 24 min. 44.316 secs.	Long: W 104.449 deg. OR W -105 deg. 33 min. 4.284 secs.		
Contractor:	Rig/Platform Name/Num:		
Job Purpose: Recement Service	Job Type: Recement Service	Ticket Amount:	
Well Type: Development Well	Svc Supervisor: SNYDER, JONATHAN	MBU ID Emp #: 435616	
Sales Person: FLING, MATTHEW			

Activity Description	Date/Time	Cht #	Rate		Volume		Pressure		Comments
			bbl/min	min	bbl	Total	Tubing	Casing	
Arrive at Location from Service Center	01/16/2012 06:30								ARRIVED AND CONDUCTED A HAZARD HUNT AND FOUND NO HAZARDS THAT CONFLICT WITH US RIGGING UP EQUIPMENT.
Pre-Job Safety Meeting	01/16/2012 07:45								HELD SAFETY MEETING WITH ALL EMPLOYEES AND ALL THIRD PARTY PERSONEL PRIOR TO PUMPING THE CEMENT JOB. WAITED WHILE A BAG OF MUDFLUSH WAS BROUGHT OUT TO LOCATION
Start Job	01/16/2012 09:29								HELD SAFETY MEETING WITH ALL EMPLOYEES PRIOR TO RIGGING DOWN AND DISCUSSED ALL HAZARDS WHILE RIGGING DOWN EQUIPMENT.
Test Lines	01/16/2012 09:29								PRESSURE TEST LINES TO 3500 PSI
Pump Spacer 1	01/16/2012 09:32		2		10			1299.	W/ RIG WATER
Pump Spacer 2	01/16/2012 09:37		2		12			1361.	MUDFLUSH SPACER
Pump Spacer 1	01/16/2012 09:43		2		10			1350.	W/ RIG WATER
Activity Description	Date/Time	Cht	Rate bbl/min		Volume bbl			Pressure psig	Comments

Sold To #: 304535

Ship To #: 2285832

Quote #:

Sales Order #:

9201364

SUMMIT Version: 7.2.27

Monday, January 16, 2012 12:08:00

Cementing Job Log

		#	Stage	Total	Tubing	Casing	
Pump Cement	01/16/2012 09:49		2	96		1345. 0	248 SKS SURFACE VARICEM CEMENT MIXED @ 12 PPG W/ RIG WATER
Pump Displacement	01/16/2012 10:39		1.5	1.5		1985. 0	W/ RIG WATER
Shutdown	01/16/2012 10:40						SHUTDOWN AND WAITED WHILE RIG CREW PULLED 49 JOINTS OF TUBING.
Pump Cement	01/16/2012 11:16		2	45		1109. 0	116 SKS SURFACE VARICEM CEMENT MIXED @ 12 PPG W/ RIG WATER, GOT CEMENT RETURNS BACK AT 45 BBLs OF CEMENT AWAY IN THE SECOND STAGE.
Pump Displacement	01/16/2012 11:40		2	0.5		1210. 0	W/ RIG WATER
End Job	01/16/2012 11:42						
Pre-Rig Down Safety Meeting	01/16/2012 12:00						HELD SAFETY MEETING WITH ALL EMPLOYEES PRIOR TO RIGGING DOWN AND DISCUSSED ALL HAZARDS WHILE RIGGING DOWN EQUIPMENT.
Depart Location for Service Center or Other Site	01/16/2012 13:00						HELD SAFETY MEETING PRIOR TO LEAVING LOCATION AND DISCUSSED ALL POTENTIAL HAZARDS WHILE DRIVING BACK TO THE SERVICE CENTER.

Sold To #: 304535

Ship To #: 2285832

Quote #:


Sales Order #:

9201364

SUMMIT Version: 7.2.27

Monday, January 16, 2012 12:08:00

PDC NATIONAL HOG FARM 13-9
SO# 9201364 RE-CEMENT



Global Event Log									
Intersection		TID	TIP	Intersection	TID	TIP			
2	Start Job	09:29:43	8.336	3767	3	Test Lines	09:29:49	8.381	3757
4	Pump Water	09:32:50	8.361	1299	5	Pump MudFlush III	09:37:19	8.317	1361
6	Pump Water	09:43:52	8.318	1350	7	Pump Cement @ 12#	09:49:41	9.580	1345
8	Pump Displacement	10:39:26	10.52	2108	9	Shutdown	10:40:06	8.364	98.84
10	Pump Cement @ 12 #	11:16:21	9.319	367.9	11	Pump Displacement	11:40:20	11.77	1210
12	End Job	11:42:22	9.015	10.000					

Customer: PDC	Job Date: 16-Jan-2012	Sales Order #: 9201364
Well Description: NATIONAL HOG FARM 13-9	UWI: 05-123-20921-00	
SERVICE SUPERVISOR JONATHAN SNYDER	SERVICE OPERATOR JAMES WILEY	