

|                               |  |  |             |
|-------------------------------|--|--|-------------|
| <b>FORM INSP</b><br>Rev 05/11 | <b>State of Colorado</b><br><b>Oil and Gas Conservation Commission</b><br>1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109 |  | DE ET OE ES |
|-------------------------------|--|--|-------------|

Inspection Date: 02/24/2012  
 Document Number: 662300230  
 Overall Inspection: Satisfactory

**FIELD INSPECTION FORM**

|                     |               |               |               |                                     |
|---------------------|---------------|---------------|---------------|-------------------------------------|
| Location Identifier | Facility ID   | Loc ID        | Tracking Type | Inspector Name: <u>NEIDEL, KRIS</u> |
|                     | <u>290935</u> | <u>335629</u> |               |                                     |

**Operator Information:**

OGCC Operator Number: 96155 Name of Operator: WHITING OIL AND GAS CORPORATION  
 Address: 1700 BROADWAY STE 2300  
 City: DENVER State: CO Zip: 80290

**Contact Information:**

| Contact Name | Phone          | Email                   | Comment          |
|--------------|----------------|-------------------------|------------------|
| Lawson, Gary | (970) 878-4096 | Gary.Lawson@whiting.com | EH&S Coordinator |

**Compliance Summary:**

QtrQtr: NWNW Sec: 29 Twp: 2S Range: 97W

**Inspector Comment:**

\_\_\_\_\_

**Related Facilities:**

| Facility ID | Type     | Status | Status Date | Well Class | API Num   | Facility Name       |                                     |
|-------------|----------|--------|-------------|------------|-----------|---------------------|-------------------------------------|
| 290935      | WELL     | PR     | 03/18/2008  | GW         | 103-11032 | BOIES A29D-20M2     | <input checked="" type="checkbox"/> |
| 290937      | WELL     | PR     | 06/18/2008  | OG         | 103-11029 | BOIES A-29D-D2      | <input checked="" type="checkbox"/> |
| 291116      | WELL     | PR     | 04/28/2008  | OG         | 103-11036 | BOIES A-29D-20M4    | <input checked="" type="checkbox"/> |
| 291961      | WELL     | PR     | 06/30/2008  | OG         | 103-11068 | BOIES A-29D-D3      | <input checked="" type="checkbox"/> |
| 335629      | LOCATION | AC     | 04/14/2009  |            | -         | BOIES-62S97W 29NWNW | <input type="checkbox"/>            |

**Equipment:** Location Inventory

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

**Signs/Marker:**

| Type     | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|----------|-----------------------------|---------|-------------------|---------|
| WELLHEAD | Satisfactory                |         |                   |         |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

|  |      |        |                   |         |
|--|------|--------|-------------------|---------|
| <b>Spills:</b>   |      |        |                   |         |
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

|                   |   |                             |         |                   |         |
|-------------------|---|-----------------------------|---------|-------------------|---------|
| <b>Equipment:</b> |   |                             |         |                   |         |
| Type              | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Dehydrator        | 4 | Satisfactory                |         |                   |         |
| Gas Meter Run     | 1 | Satisfactory                |         |                   |         |

|                     |              |                                   |                |                  |
|---------------------|--------------|-----------------------------------|----------------|------------------|
| <b>Tanks/Berms:</b> |              | <input type="checkbox"/> New Tank | Tank ID: _____ |                  |
| Contents            | #            | Capacity                          | Type           | SE GPS           |
| PRODUCED WATER      | 2            | 400 BBLS                          | STEEL AST      | ,                |
| S/U/V:              | Satisfactory | Comment:                          |                |                  |
| Corrective Action:  |              |                                   |                | Corrective Date: |

Paint

|           |          |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

|                   |          |                     |                     |                 |
|-------------------|----------|---------------------|---------------------|-----------------|
| Type              | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance     |
| Metal             | Adequate | Walls Sufficient    | Base Sufficient     | Adequate        |
| Corrective Action |          |                     |                     | Corrective Date |
| Comment           |          |                     |                     |                 |

|                     |              |                                   |                |                  |
|---------------------|--------------|-----------------------------------|----------------|------------------|
| <b>Tanks/Berms:</b> |              | <input type="checkbox"/> New Tank | Tank ID: _____ |                  |
| Contents            | #            | Capacity                          | Type           | SE GPS           |
| CONDENSATE          | 2            | 400 BBLS                          | STEEL AST      | ,                |
| S/U/V:              | Satisfactory | Comment:                          |                |                  |
| Corrective Action:  |              |                                   |                | Corrective Date: |

Paint

|           |          |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

|                   |          |                     |                     |                 |
|-------------------|----------|---------------------|---------------------|-----------------|
| Type              | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance     |
| Metal             | Adequate | Walls Sufficient    | Base Sufficient     | Adequate        |
| Corrective Action |          |                     |                     | Corrective Date |
| Comment           |          |                     |                     |                 |

|                 |         |
|-----------------|---------|
| <b>Venting:</b> |         |
| Yes/No          | Comment |
| NO              |         |

| <b>Flaring:</b> |                             |         |                   |         |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type            | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|                 |                             |         |                   |         |

**Predrill**

Location ID: 335629

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_ Pads: \_\_\_\_\_ Soil Stockpile: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**Wildlife BMPs:**

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_  
 Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_  
 Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Well**

|                            |                              |                   |                         |
|----------------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>290935</u> | API Number: <u>103-11032</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>290937</u> | API Number: <u>103-11029</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>291116</u> | API Number: <u>103-11036</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>291961</u> | API Number: <u>103-11068</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:** \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_  
DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:** \_\_\_\_\_

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_  
Comment: \_\_\_\_\_  
Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

Inspector Name: NEIDEL, KRIS

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_