

FORM
INSPRev
05/11State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Inspection Date:

03/13/2012

Document Number:

668100018

Overall Inspection:

Satisfactory

FIELD INSPECTION FORM

Location Identifier Facility ID Loc ID Tracking Type
 420154 420164 Inspector Name: KELLERBY, SHAUN

Operator Information:

OGCC Operator Number: 10335 Name of Operator: AXIA ENERGY LLC

Address: 1430 LARIMER STREET #400

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Holder, Jerry	970-261-0218	jholder@axiaenergy.com	Production Superintendent

Compliance Summary:

QtrQtr: SWSE Sec: 23 Twp: 9S Range: 95W

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
420154	WELL	XX	10/31/2010		077-10116	Kimball Creek 23-214MD-995	X
420157	WELL	XX	10/31/2010		077-10117	Kimball Creek 23-307D-995	X
420159	WELL	XX	10/31/2010		077-10118	Kimball Creek 24-106D-995	X
420160	WELL	WO	04/04/2011		077-10119	Kimball Creek 23-412D-995	X
420161	WELL	WO	04/21/2011		077-10120	Kimball Creek 23-210D-995	X
420163	WELL	XX	10/31/2010		077-10121	Kimball Creek 24-114D-995	X
420164	LOCATION	AC	10/31/2010		-	Kimball Creek Pad 23-4C-995	
427689	TANK BATTERY	AC	10/31/2010		-	Kimball Creek Pad 23-4C-995	

Equipment:

Location Inventory

Special Purpose Pits: _____ Drilling Pits: 1 Wells: 6 Production Pits: _____
 Condensate Tanks: 2 Water Tanks: 2 Separators: 2 Electric Motors: _____
 Gas or Diesel Mortors: _____ Cavity Pumps: _____ LACT Unit: _____ Pump Jacks: _____
 Electric Generators: _____ Gas Pipeline: 1 Oil Pipeline: _____ Water Pipeline: 2
 Gas Compressors: _____ VOC Combustor: 1 Oil Tanks: _____ Dehydrator Units: _____
 Multi-Well Pits: _____ Pigging Station: _____ Flare: _____ Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Unsatisfactory	No NFPA label on tanks	Install sign to comply with rule 210.b.	03/31/2012

Inspector Name: KELLERBY, SHAUN

WELLHEAD	Unsatisfactory	No signs at the well head	Install sign to comply with rule 210.b.	03/31/2012
----------	----------------	---------------------------	---	------------

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
STORAGE OF SUPL	Unsatisfactory	Supplies and equipment stored on the pad site.	Remove all items not needed for the production of the lease as required by 603.j	03/31/2012

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Horizontal Separator	2	Satisfactory			

Tanks/Berms: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST	,

S/U/V: Unsatisfactory Comment: Place required labels on all tanks

Corrective Action: No NFPA label on tanks Corrective Date: 03/31/2012

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Adequate

Corrective Action _____ Corrective Date _____

Comment _____

Tanks/Berms: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST	39.259980,107.962180

S/U/V:		Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	
-----------	--

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

<u>Venting:</u>	
Yes/No	Comment
NO	

<u>Flaring:</u>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 420164

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	kubeczkod	Location is in a sensitive area because of proximity to surface water; therefore, operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations; including, but not limited to, construction of a berm or diversion dike, diversion/collection trenches within and/or outside of berms/dikes, site grading, or other comparable measures sufficiently protective of nearby surface water.	09/20/2010
OGLA	kubeczkod	Operator must implement best management practices to contain any unintentional release of fluids.	09/20/2010

Wildlife BMPs:**Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 420154 API Number: 077-10116 Status: XX Insp. Status: ND

Facility ID: 420157 API Number: 077-10117 Status: XX Insp. Status: ND

Facility ID: 420159 API Number: 077-10118 Status: XX Insp. Status: ND

Inspector Name: KELLERBY, SHAUN

Facility ID: 420160	API Number: 077-10119	Status: WO	Insp. Status: PR
Facility ID: 420161	API Number: 077-10120	Status: WO	Insp. Status: PR
Facility ID: 420163	API Number: 077-10121	Status: XX	Insp. Status: ND

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND

Comment: Large area of pad not reclaimed

1003a. Debris removed? CM CA CA Date

Waste Material Onsite? CM CA CA Date

Unused or unneeded equipment onsite? CM CA CA Date

Pit, cellars, rat holes and other bores closed? CM CA CA Date

Guy line anchors removed? CM CA CA Date

Guy line anchors marked? CM CA CA Date

1003b. Area no longer in use? Production areas stabilized ?

Inspector Name: KELLERBY, SHAUN

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail					

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: Berms on pad site have no BMP to control erosion

CA: _____