

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

03/20/2012

Document Number:

668100028

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: KELLERBY, SHAUN
	421397	421390		

Operator Information:OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Friesen, Kathy	970-285-2665	Kathy.Friesen@EnCana.com	

Compliance Summary:QtrQtr: SENW Sec: 12 Twp: 7S Range: 92W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
421387	WELL	XX	01/31/2011		045-20385	TWIN CREEK 12-5A2 (F12E)	
421388	WELL	XX	01/31/2011		045-20386	TWIN CREEK 12-3D1 (F12E)	
421389	WELL	XX	01/31/2011		045-20387	TWIN CREEK 12-4D1 (F12E)	
421390	LOCATION	AC	01/31/2011		-	Twin Creek 12-6C1 (F12E)	
421393	WELL	XX	01/31/2011		045-20388	TWIN CREEK 12-5D1 (F12E)	
421394	WELL	XX	01/31/2011		045-20389	TWIN CREEK 12-4A1 (F12E)	
421395	WELL	XX	01/31/2011		045-20390	TWIN CREEK 12-5A1 (F12E)	
421396	WELL	XX	01/31/2011		045-20391	TWIN CREEK 12-6C1 (F12E)	
421397	WELL	XX	01/31/2011		045-20392	TWIN CREEK 12-3D2 (F12E)	X
421398	WELL	XX	01/31/2011		045-20393	TWIN CREEK 12-6D1 (F12E)	
421400	WELL	XX	01/31/2011		045-20394	TWIN CREEK 12-6A1 (F12E)	

Equipment:Location Inventory

Special Purpose Pits: <u>1</u>	Drilling Pits: <u> </u>	Wells: <u>10</u>	Production Pits: <u> </u>
Condensate Tanks: <u> </u>	Water Tanks: <u> </u>	Separators: <u>10</u>	Electric Motors: <u> </u>
Gas or Diesel Mortors: <u> </u>	Cavity Pumps: <u> </u>	LACT Unit: <u> </u>	Pump Jacks: <u> </u>
Electric Generators: <u> </u>	Gas Pipeline: <u>1</u>	Oil Pipeline: <u> </u>	Water Pipeline: <u>1</u>
Gas Compressors: <u> </u>	VOC Combustor: <u> </u>	Oil Tanks: <u> </u>	Dehydrator Units: <u> </u>
Multi-Well Pits: <u> </u>	Pigging Station: <u> </u>	Flare: <u> </u>	Fuel Tanks: <u> </u>

LocationEmergency Contact Number: (S/U/V) Corrective Date:

Inspector Name: KELLERBY, SHAUN

Comment:	
Corrective Action:	

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 421390

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
Agency	kubeczkod	Operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations. If fluids are conveyed via pipeline, operator must implement best management practices to contain any unintentional release of fluids.	06/16/2010
Agency	kubeczkod	The moisture content of any drill cuttings in a cuttings pit, trench, or pile shall be as low as practicable to prevent accumulation of liquids greater than de minimis amounts. At the time of closure, the drill cuttings must also meet the applicable standards of table 910-1.	06/16/2010
Agency	kubeczkod	Location is in a sensitive area because of proximity to a domestic water well; therefore either a lined drilling pit or closed loop system must be implemented.	06/16/2010
Agency	kubeczkod	Location is in a sensitive area because of proximity to a domestic water well; therefore production pits (if constructed) must be lined.	06/16/2010
Agency	kubeczkod	No portion of any pit that will be used to hold liquids shall be constructed on fill material, unless the pit and fill slope are designed and certified by a professional engineer, subject to review and approval by the director prior to construction of the pit. The construction and lining of the pit shall be supervised by a professional engineer or their agent. The entire base of the pit must be in cut.	05/25/2010

Wildlife BMPs:

Stormwater:**Comment:****Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____
 Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Well**

Facility ID: 421397 API Number: 045-20392 Status: XX Insp. Status: DG

Well Drilling

Rig: Rig Name: M15 Pusher/Rig Manager: _____
 Permit Posted: Satisfactory Access Sign: Satisfactory

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids**Management:**

Lined Pit: NO Unlined Pit: NO Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: _____

Comment:

Fit TVD 1174' tested to 134psi 0 psi loss at min. Passed

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Complaint:

Tracking Num	Category	Assigned To	Description	Incident Date
200340195	ODOR	LONGWORTH, MIKE	Near by residents noticing a chemical odor in the mourning hours coming from Nabors M15 rig.	02/13/2012

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IRRIGATED

Comment: _____

1003a. Debris removed? _____ CM _____ CA _____ CA Date _____

Waste Material Onsite? _____ CM _____ CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____ CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____ CA _____ CA Date _____

Guy line anchors removed? _____ CM _____ CA _____ CA Date _____

Guy line anchors marked? _____ CM _____ CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Inspector Name: KELLERBY, SHAUN

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: IRRIGATED _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____

Corrective Date: _____

Comment: _____

CA: _____