

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/02/2012

Document Number:

662300395

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>NEIDEL, KRIS</u>
	<u>324634</u>	<u>324634</u>		

**Operator Information:**OGCC Operator Number: 100200 Name of Operator: LONE PINE GAS INCAddress: 6704 E LONG AVECity: ENGLEWOODState: COZip: 80112**Contact Information:****Compliance Summary:**QtrQtr: SWSE Sec: 28 Twp: 9N Range: 81W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/03/2012	662300113			V			Y

**Inspector Comment:**

On location as result of public complaint Document number 200326783. See complaint for information regarding discharge. Crews on location to bring field into compliance, work is ongoing everywhere. Entire field is shut-in, the separation facility is all being re-evaluated and cleaned. All of the flow lines are being traced to figure out where everything is going to. 'vent pit' is in the process of being emptied and closed. Inspector has advised operator to review rule 912 while planning future plan for gas use.

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
212138	WELL	PR	02/01/2011	OW	057-06031	MARGARET SPAULDING 4	<input checked="" type="checkbox"/>
212154	WELL	SI	06/15/1984	DSPW	057-06047	MARGARET SPAULDING 4-B	<input checked="" type="checkbox"/>
212215	WELL	PR	07/19/1974	OW	057-06108	MARGARET SPAULDING 14	<input checked="" type="checkbox"/>
324634	LOCATION	AC	04/14/2009		-	MARGARET SPAULDING-69N81W 28SWSE	<input type="checkbox"/>
427281	TANK BATTERY	AC	01/10/2012		-	M. SPAULDING CENTRALIZED TANK BATT 1	<input type="checkbox"/>

**Equipment:****Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**Emergency Contact Number: (S/U/V) \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Inspector Name: NEIDEL, KRIS

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Venting:</b>	
Yes/No	Comment

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 324634

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

**Comment:** \_\_\_\_\_

**Staking:**

**On Site Inspection (305):**

**Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:**

**Summary of Operator Response to Landowner Issues:**

**Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

**Well**

Facility ID: 212138 API Number: 057-06031 Status: PR Insp. Status: SI

Inspector Name: NEIDEL, KRIS

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\oFormP  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\oFormP

Facility ID: 212154 API Number: 057-06047 Status: SI Insp. Status: SI

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\oFormP  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\oFormP

Facility ID: 212215 API Number: 057-06108 Status: PR Insp. Status: SI

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\oFormP  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\oFormP

### Environmental

#### Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

#### Water Well:

Lat Long

DWR Receipt Num: Owner Name: GPS :

#### Field Parameters:

Sample Location:

<b>Complaint:</b>				
Tracking Num	Category	Assigned To	Description	Incident Date
200344906	SPILLS	FISCHER, ALEX	<p>At approximatley 5:25pm on March 29, 2012 I was travelling West on Jackson County Road 12W. I was approaching the T-intersection where Jackson County Road 12W splits into Jackson County Road 12W and Jackson County Road 16. At the T the asphalt ends, and both roads are gravel. This T-intersection is also the entrance to the North Fork Ranch.</p> <p>As I was approaching the intersection, I observed a tanker-type semi-truck stopped on the asphalt. I observed a single male walk from the back of the vehicle to the driver door, enter the semi and start moving toward me. As we passed each other on the roadway (the semi heading East, I heading West), i observed a large fan-shaped discharge of water-like substance spraying from the back of the vehicle. At the same time I also smelled a strong oil/hydrocarbon odor. I stopped my vehicle near the T-intersection and stepped out. The odor was stronger at this time, and I observed a sirty-water like substance on the roadway. I liiked East toward the semi-travelling away from my location and observed the water-like spray continuing to come from the back of the vehicle until the vehicledrove out of site over a samll rise approximately 1/4 mile away. I also observed, along with the very wet roadway, numerous paint-chip type items distributed along the roadway and roadway edge, as well as one piece of aquatic-type vegetation on the asphalt. I followed fresh vehicle tracks, and small, wet stram of liquid from Jackson County Road 12W to Jackson County Road 16 to the entrance to the Lone Pine field. I drove home, made some phone calss for assistance-one to Alex Fischer, leaving a message. I then returned to the site, took representaive photos of the spill and adjoining landscape, and obtained two samples. One sample a white-paint chip type of substance, the second a sample of an aquatic-type vegetation on the asphalt roadway. Phots were taken of eac item before retrieving. Each item was placed in an individual plastic baggie and labeled with my initials, the date and time of collection with a sharpie marker. The folowwing morning, Friday, march 30, 1012, ad approximately 9:00a.m. I contacted Mr. Fischer and relaated then information above. He requested an incident report at theat time and provided the informatio to fill out this form.</p>	03/30/2012

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

Inspector Name: NEIDEL, KRIS

<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_