

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/10/2012

Document Number:

668400087

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>221577</u>	<u>334449</u>		<u>BROWNING, CHUCK</u>

**Operator Information:**

OGCC Operator Number:	<u>16800</u>	Name of Operator:	<u>DELTA PETROLEUM CORPORATION</u>
Address:	<u>370 17TH ST STE 4300</u>		
City:	<u>DENVER</u>	State:	<u>CO</u>
		Zip:	<u>80202</u>

**Contact Information:**

Contact Name	Phone	Email	Comment
Macke, Brian	303-575-0386	bmacke@deltapetro.com	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

**Compliance Summary:**

QtrQtr:	<u>SENW</u>	Sec:	<u>10</u>	Twp:	<u>10S</u>	Range:	<u>93W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/13/2012	659700094	PR	PR	S			N
08/05/2011	200318500	SR	PR	U			Y
04/06/2007	200109200	PR	SI	U	I	F	Y
09/27/2005	200083064	PR	SI	S		P	N
10/28/1999	500154137	ID	TA			P	N

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
221577	WELL	PR	01/06/1980		077-08179	VEGA UNIT 3	X
277411	LEASE	PR	04/19/2005		-	VEGA UNIT 3	
278834	WELL	PR	06/23/2008	GW	077-08927	VEGA UNIT 10-22	X
278835	WELL	PR	12/18/2005	GW	077-08926	VEGA 10-32	X
278903	WELL	PR	12/31/2005	GW	077-08934	VEGA 10-23	X
278904	WELL	PR	06/23/2008	OW	077-08933	VEGA UNIT 10-33	X
289433	WELL	PR	02/22/2007	LO	077-09245	VEGA UNIT 10-324	X
289434	WELL	PR	12/11/2007	GW	077-09244	VEGA UNIT 10-214	X
289435	WELL	PR	12/11/2007	GW	077-09243	VEGA UNIT 10-114	X
289436	WELL	PR	02/22/2007	LO	077-09242	VEGA UNIT 10-124	X
289437	WELL	PR	01/09/2008	GW	077-09241	VEGA UNIT 10-134	X
334449	LOCATION	AC	04/14/2009		-	VEGA UNIT-610S93W 10SWNE	

**Equipment:**Location Inventory

Inspector Name: BROWNING, CHUCK

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

### Location

#### Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory			
BATTERY	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

#### Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

#### Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

#### Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Horizontal Heated Separator	4	Satisfactory			
Emission Control Device	1	Satisfactory			
Gas Meter Run	1	Satisfactory			

Inspector Name: BROWNING, CHUCK

<b>Facilities:</b>		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	3	300 BBLS	STEEL AST	39.205390,-107.754650	
S/U/V:	Satisfactory		Comment:		
Corrective Action:				Corrective Date:	
<b>Paint</b>					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
<b>Venting:</b>					
Yes/No		Comment			
<b>Flaring:</b>					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

**Predrill**

Location ID: 334449

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_**Date:** \_\_\_\_\_**Wildlife BMPs:****Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_**Date:** \_\_\_\_\_**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 221577 API Number: 077-08179 Status: PR Insp. Status: PR

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa

Facility ID: 278834 API Number: 077-08927 Status: PR Insp. Status: PR

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa

Facility ID: 278835 API Number: 077-08926 Status: PR Insp. Status: PR

Inspector Name: BROWNING, CHUCK

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\FarmPa  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\FarmPa

Facility ID: 278903 API Number: 077-08934 Status: PR Insp. Status: PR

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\FarmPa  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\FarmPa

Facility ID: 278904 API Number: 077-08933 Status: PR Insp. Status: PR

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\FarmPa  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\FarmPa

Facility ID: 289433 API Number: 077-09245 Status: PR Insp. Status: PR

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\FarmPa  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\FarmPa

Facility ID: 289434 API Number: 077-09244 Status: PR Insp. Status: PR

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\FarmPa  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\FarmPa

Facility ID: 289435 API Number: 077-09243 Status: PR Insp. Status: PR

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\FarmPa  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\FarmPa

Facility ID: 289436 API Number: 077-09242 Status: PR Insp. Status: PR

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\FarmPa  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\FarmPa

Facility ID: 289437 API Number: 077-09241 Status: PR Insp. Status: PR

Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\FarmPa  
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\FarmPa

### Environmental

#### Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:  
Comment:  
Corrective Action: Date:  
Reportable: GPS: Lat Long  
Proximity to Surface Water: Depth to Ground Water:

#### Water Well:

Lat Long  
DWR Receipt Num: Owner Name: GPS :

#### Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:  
Pilot: Wildlife Protection Devices (fired vessels):

### Reclamation - Storm Water - Pit

#### Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:  
Land Use:  
Comment:

1003a.	Debris removed? <u>Pass</u> CM _____ CA _____ CA Date _____ Waste Material Onsite? <u>Pass</u> CM _____ CA _____ CA Date _____ Unused or unneeded equipment onsite? <u>Pass</u> CM _____ CA _____ CA Date _____ Pit, cellars, rat holes and other bores closed? <u>Pass</u> CM _____ CA _____ CA Date _____ Guy line anchors removed? <u>Pass</u> CM _____ CA _____ CA Date _____ Guy line anchors marked?                  CM _____ CA _____ CA Date _____
1003b.	Area no longer in use? <u>Pass</u> Production areas stabilized ? <u>Pass</u>
1003c.	Compacted areas have been cross ripped? <u>Pass</u>
1003d.	Drilling pit closed? <u>Pass</u> Subsidence over on drill pit? <u>Pass</u>  Cuttings management: _____
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>Pass</u> Production areas have been stabilized?                  Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____ Perennial forage re-established _____
<u>Non-Cropland</u>	
Top soil replaced _____	Recontoured _____ 80% Revegetation _____
1003 f.	Weeds Noxious weeds?                  P _____
Comment: <div style="border: 1px solid black; height: 20px;"></div>	
Overall Interim Reclamation <u>Pass</u>	

Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: _____	
Reminder: _____	
Comment:	<div style="border: 1px solid black; height: 40px;"></div>
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads _____	Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____	
Location and associated production facilities reclaimed _____	Locations, facilities, roads, recontoured _____
Compaction alleviation _____	Dust and erosion control _____
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
Comment:	<div style="border: 1px solid black; height: 40px;"></div>

Inspector Name: BROWNING, CHUCK

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
------------------	-----------------	-------------------------	-----------------------	---------------	--------------------------	---------

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment:

CA: