

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/12/2012

Document Number:

663800262

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>293683</u>	<u>335807</u>		<u>LONGWORTH, MIKE</u>

Operator Information:OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Friesen, Kathy	970-285-2665	Kathy.Friesen@EnCana.com	

Compliance Summary:QtrQtr: NESE Sec: 30 Twp: 5S Range: 95W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
280531	WELL	PR	10/08/2006	GW	045-11277	N.PARACHUTE EFO6B I30A 595	<input checked="" type="checkbox"/>
280532	WELL	PR	10/06/2006	GW	045-11278	N.PARACHUTE EF06D I30A 595	<input checked="" type="checkbox"/>
280533	WELL	PR	02/01/2011	GW	045-11279	N.PARACHUTE EF07B I30A 595	<input checked="" type="checkbox"/>
280534	WELL	PR	08/15/2006	LO	045-11280	N.PARACHUTE EF07D I30A 595	<input checked="" type="checkbox"/>
280535	WELL	PR	08/11/2006	LO	045-11281	N.PARACHUTE EF01B I30A 595	<input checked="" type="checkbox"/>
280536	WELL	PR	08/14/2006	LO	045-11282	N.PARACHUTE EF02B I30A 595	<input checked="" type="checkbox"/>
280537	WELL	PR	08/11/2006	LO	045-11283	N.PARACHUTE EF02D I30A 595	<input checked="" type="checkbox"/>
280538	WELL	PR	09/27/2006	GW	045-11284	N.PARACHUTE EF03D I30A 595	<input checked="" type="checkbox"/>
293553	WELL	PR	08/09/2008	GW	045-15048	N. PARACHUTE EF05A-32 I30A 5	<input checked="" type="checkbox"/>
293554	WELL	PR	10/13/2008	GW	045-15049	N. PARACHUTE EF05C-32 I30A 5	<input checked="" type="checkbox"/>
293555	WELL	PR	03/27/2008	OW	045-15050	N. PARACHUTE EF04C-32 I30A 5	<input checked="" type="checkbox"/>
293556	WELL	PR	09/19/2007	GW	045-15051	N. PARACHUTE EF02C-30 I30A 5	<input checked="" type="checkbox"/>
293557	WELL	PR	02/01/2011	LO	045-15047	N. PARACHUTE EF16A-30 I30A 5	<input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

293558	WELL	PR	08/09/2008	GW	045-15046	N. PARACHUTE EF02A-30-I30A 5	X
293559	WELL	PR	11/19/2007	LO	045-15059	N. PARACHUTE EF15D-19 I30A 5	X
293560	WELL	PR	08/14/2009	LO	045-15060	N. PARACHUTE EF15C-19 I30A 5	X
293680	WELL	PR	10/13/2008	GW	045-15096	N. PARACHUTE EF03C-30 I30A 5	X
293681	WELL	PR	10/06/2008	OW	045-15097	N. PARACHUTE EF03A-30 I30A 5	X
293682	WELL	PR	10/11/2008	GW	045-15098	N. PARACHUTE EF03B-30 I30A 5	X
293683	WELL	PR	10/14/2008	GW	045-15099	N. PARACHUTE EF06A-30 I30A 5	X
293684	WELL	PR	10/06/2008	GW	045-15100	N. PARACHUTE EF06C-30 I30A 5	X
293685	WELL	PR	08/09/2008	GW	045-15101	N. PARACHUTE EF07A-30 I30A 5	X
293686	WELL	PR	10/12/2008	OW	045-15102	N. PARACHUTE EF07C-30 I30A 5	X
293687	WELL	PR	10/03/2008	GW	045-15103	N. PARACHUTE EF16C-30 I30A 5	X
293688	WELL	PR	10/03/2008	GW	045-15104	N. PARACHUTE EF01A-31 I30A 5	X
293689	WELL	PR	10/13/2008	GW	045-15105	N. PARACHUTE EF01C-31 I30A 5	X
293690	WELL	PR	09/01/2008	GW	045-15106	N. PARACHUTE EF05D-32 I30A 5	X
293691	WELL	PR	08/09/2008	GW	045-15107	N. PARACHUTE EF14D-19 I30A 5	X
335807	LOCATION	AC	04/14/2009		-	N.PARACHUTE-65S95W 30NESE	
425548	PIT		09/19/2011		-	I30A 595	

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Main	Satisfactory			

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
CONTAINERS	Satisfactory			
BATTERY	Satisfactory			

Inspector Name: LONGWORTH, MIKE

WELLHEAD	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TRASH	Unsatisfactory	bottles, tumble weeds, tread protectors, wood blocks, well head nuts, etc	pick up trash	05/04/2012

Spills:				
Type	Area	Volume	Corrective action	CA Date
Lube Oil	WELLHEAD	<= 5 bbls	clean and remediate oil stains around wells	05/04/2012

☐ Multiple Spills and Releases?

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	12	Satisfactory			
Plunger Lift	20	Satisfactory			
Plunger Lift	8	Satisfactory			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST	,

S/U/V: Satisfactory Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action: _____ Corrective Date: _____

Comment: _____

Venting:

Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 335807

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____**Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 280531 API Number: 045-11277 Status: PR Insp. Status: PR

Data retrieval failed for the subreport 'Subreport9' located at: \\drdensterling\leFormP
Data retrieval failed for the subreport 'Subreport10' located at: \\drdensterling\leFormP

Inspector Name: LONGWORTH, MIKE

[illegible]

Facility ID: 293682	API Number: 045-15098	Status: PR	Insp. Status: PR
Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa			
Facility ID: 293683	API Number: 045-15099	Status: PR	Insp. Status: PR
Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa			
Facility ID: 293684	API Number: 045-15100	Status: PR	Insp. Status: PR
Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa			
Facility ID: 293685	API Number: 045-15101	Status: PR	Insp. Status: PR
Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa			
Facility ID: 293686	API Number: 045-15102	Status: PR	Insp. Status: PR
Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa			
Facility ID: 293687	API Number: 045-15103	Status: PR	Insp. Status: PR
Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa			
Facility ID: 293688	API Number: 045-15104	Status: PR	Insp. Status: PR
Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa			
Facility ID: 293689	API Number: 045-15105	Status: PR	Insp. Status: PR
Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa			
Facility ID: 293690	API Number: 045-15106	Status: PR	Insp. Status: PR
Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa			
Facility ID: 293691	API Number: 045-15107	Status: PR	Insp. Status: PR
Data retrieval failed for the subreport 'Subreport0' located at: \\dardensterling\leFormPa Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\leFormPa			

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Inspector Name: LONGWORTH, MIKE

Access Roads Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
Compaction alleviation _____ Dust and erosion control _____
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
Weeds present _____ Subsidence _____
Comment: _____
Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____