

FORM
5

Rev
02/08

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

2588328

Date Received:

08/29/2011

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type Final completion Preliminary completion

1. OGCC Operator Number: 96850 4. Contact Name: MATT BARBER
2. Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC Phone: (303) 606-4385
3. Address: 1001 17TH STREET - SUITE #1200 Fax: (303) 629-8268
City: DENVER State: CO Zip: 80202

5. API Number 05-045-18294-00 6. County: GARFIELD
7. Well Name: Mahaffey Well Number: PA 44-25
8. Location: QtrQtr: SESW Section: 25 Township: 6S Range: 95W Meridian: 6
Footage at surface: Distance: 684 feet Direction: FSL Distance: 2351 feet Direction: FWL
As Drilled Latitude: 39.490478 As Drilled Longitude: -107.947985

GPS Data:

Data of Measurement: 10/07/2009 PDOP Reading: 2.2 GPS Instrument Operator's Name: W. KIRKPATRICK

** If directional footage at Top of Prod. Zone Dist.: 1173 feet. Direction: FSL Dist.: 629 feet. Direction: FEL
Sec: 25 Twp: 6S Rng: 95W

** If directional footage at Bottom Hole Dist.: 1116 feet. Direction: FSL Dist.: 620 feet. Direction: FEL
Sec: 25 Twp: 6S Rng: 95W

9. Field Name: PARACHUTE 10. Field Number: 67350
11. Federal, Indian or State Lease Number:

12. Spud Date: (when the 1st bit hit the dirt) 09/03/2010 13. Date TD: 09/10/2010 14. Date Casing Set or D&A: 09/11/2010

15. Well Classification:

Dry Oil Gas/Coalbed Disposal Stratigraphic Enhanced Recovery Storage Observation

16. Total Depth MD 8355 TVD** 7850 17 Plug Back Total Depth MD 8234 TVD** 7729

18. Elevations GR 5176 KB 5202

One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:

CBL & RESERVOIR PERFORMANCE MONITOR (RBM), MUD

20. Casing, Liner and Cement:

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	24	18		0	93	25	0	93	VISU
SURF	13+1/2	9+5/8		0	1,294	340	0	1,294	VISU
1ST	8+3/4	4+1/2		0	8,339	1,375	3,608	8,339	CBL

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____

Method used	String	Cementing tool setting/pref depth	Cement volume	Cement top	Cement bottom

Details of work:

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
GREELEY SAND	2,010		<input type="checkbox"/>	<input type="checkbox"/>	
MESAVERDE	4,664		<input type="checkbox"/>	<input type="checkbox"/>	
CAMEO	7,184		<input type="checkbox"/>	<input type="checkbox"/>	
ROLLINS	8,167		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

SURFACE PRESSURE: 0#

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: MATT BARBER

Title: SR REGULATORY SPECIALIST Date: 6/21/2011 Email: MATT.BARBER@WILLIAMS.COM

Attachment Check List

Att Doc Num	Document Name	attached ?	
Attachment Checklist			
2588330	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
2588329	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Other Attachments			
2588328	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

General Comments

User Group	Comment	Comment Date
Permit	approved w/out paper RPM log--WPX submitting soon.	4/18/2012 1:40:44 PM
Permit	MISSING RPM LOG, NO LONGER REQUESTING PER J.S.	11/17/2011 3:43:28 PM
Permit	REQ RPM HARD COPY	10/5/2011 8:27:10 AM

Total: 3 comment(s)