

Inspector Name: QUINT, CRAIG

FORM  
INSPRev  
05/11

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

05/08/2012

Document Number:

663901048

Overall Inspection:

Satisfactory

### FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name
	414701	414701		QUINT, CRAIG

#### Operator Information:

OGCC Operator Number: 10221 Name of Operator: RUNNING FOXES PETROLEUM INC

Address: 6855 S. HAVANA ST #400

City: CENTENNIAL

State: CO

Zip: 80112

#### Contact Information:

Contact Name	Phone	Email	Comment
Keppel, Kent	720-889-0510 off	kkeppel@atoka.com	
LEONARD, MIKE		mike.leonard@state.co.us	

#### Compliance Summary:

QtrQtr: NWNE Sec: 4 Twp: 14S Range: 55W

#### Inspector Comment:

#### Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
414710	WELL	AL	03/21/2012		073-06397	CRAIG 2-4	<input checked="" type="checkbox"/>

#### Equipment:

#### Location Inventory

Special Purpose Pits: _____	Drilling Pits: 1	Wells: 1	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: 1	Electric Motors: 1
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: 3	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

### Location

Emergency Contact Number: (S/U/V) \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

#### Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

#### Venting:

Yes/No	Comment

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 414701

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Comment:****CA:****Date:****Wildlife BMPs:**

BMP Type	Comment
PROPOSED BMPs	<p>RUNNING FOXES PETROLEUM INC.</p> <p>STORMWATER MANAGEMENT PRACTICES</p> <p>Reference COGCC Final Rule Amendment (December 17, 2008)</p> <p>1002. SITE PREPARATION; I. Stormwater Management A. thru F.</p> <p>RUNNING FOXES PETROLEUM, INC. (RFP) will implement the following procedures and practices to remove /reduce the possibility of discharged materials that may pollute water runoff from their field facilities, operations and well site locations. These procedures and practices, will minimize the potential of any discharge or spill that could potentially pollute surface water and any stormwater runoff.</p> <p>A. Covering materials and activities:</p> <p>RFP will cover with tarps all containers /items that have the potential for material leakage. These items, whenever possible, will be kept in a central location within the operational area.</p> <p>B. Material handling and spill prevention:</p> <p>RFP will use secondary containment methods, tarps, splash pans, or appropriate prevention items when transferring, pouring, or handling items that have the potential for spills. If items are on location for a period of time they will be on pallets off the ground.</p> <p>C. Erosion controls:</p> <p>RFP maintains and constructs well pads to minimize surface grade elevations. As season and weather changes; improvements to these well pads are adjusted accordingly. Roads, culverts, stream crossings and cut /fill slopes are prepared for runoff to be controlled and directed to desired locations.</p> <p>These controls will be constructed with the cooperation of the landowner to facilitate their use of the land. Interim Reclamation on well pads is accomplished as soon as possible to minimize the effects of erosion. Topsoil will be returned and reseeding will be completed.</p>

**D. Self- inspection, maintenance, and good housekeeping:**

RFP has a pumper on location almost everyday to identify these

factors. Site improvement and inspection is a constant factor and

monitored with the anticipation of the season and the weather. As

potential contaminants are no longer needed at a set location they are removed and disposed of or stored in a more central secured monitored area. All vehicle washing is done off site.

**E. Spill response procedures:**

RFP has a first response the standard dirt and shovel work; if the procedures described in B above don't initially contain the spill. This soil is removed from any surface water condition.

F. Vehicle tracking control procedures: RFP attempts to design and maintain all roads to minimize any rutting. All operational and access roads are on non -paved roads with low potential of sediment contributing to stormwater contamination.

**Comment:****CA:****Date:****Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:****Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility ID: 414710      API Number: 073-06397      Status: AL      Insp. Status: AL

### Environmental

#### Spills/Releases:

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment:   
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
 Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
 Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

#### Water Well:

Lat \_\_\_\_\_ Long \_\_\_\_\_  
 DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

#### Field Parameters:

Sample Location:

Emission Control Burner (ECB): \_\_\_\_\_  
 Comment: \_\_\_\_\_  
 Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

### Reclamation - Storm Water - Pit

#### Interim Reclamation:

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: RANGELAND

Comment:

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_ CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Inspector Name: QUINT, CRAIG

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

#### Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built Pass

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: **LOCATION HAS NO SIGN OF ANY GROUND DISTURBANCE, STAKE IS STILL IN PLACE.**

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation Pass

#### Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_