

Inspector Name: Baroumand, Soraya

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

05/10/2012

Document Number:

668500050

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>222330</u>	<u>391518</u>		<u>Baroumand, Soraya</u>

Operator Information:OGCC Operator Number: 2500 Name of Operator: AMOCO PRODUCTION CO.Address: P O BOX 3092 ROOM 2.554City: HOUSTON State: TX Zip: 77253-**Contact Information:**

Contact Name	Phone	Email	Comment
BAROUMAND, SORAYA		soraya.baroumand@state.co.us	

Compliance Summary:QtrQtr: SWNE Sec: 3 Twp: 5N Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/20/2006	200095020	HR	PA	S	P	P	N

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
222330	WELL	PA	03/20/2001		081-05307	GEORGE W NORVELL 1	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

LocationEmergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 391518

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 222330 API Number: 081-05307 Status: PA Insp. Status: PA

Data retrieval failed for the subreport, 'rptInsp12',

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? CM CA Date

Waste Material Onsite? CM CA Date

Unused or unneeded equipment onsite? CM CA Date

Pit, cellars, rat holes and other bores closed? CM CA Date

Guy line anchors removed? CM CA Date

Guy line anchors marked? CM CA Date

1003b. Area no longer in use? Production areas stabilized ?

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Subsidence over on drill pit?

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized? Segregated soils have been replaced?

RESTORATION AND REVEGETATION**Cropland**

Top soil replaced Recontoured Perennial forage re-established

Non-Cropland

Top soil replaced Recontoured 80% Revegetation

1003 f. Weeds Noxious weeds?

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Inspector Name: Baroumand, Soraya

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass
Debris removed Pass No disturbance /Location never built Pass
Access Roads Regraded Pass Contoured Pass Culverts removed Pass
Gravel removed Pass
Location and associated production facilities reclaimed Pass Locations, facilities, roads, recontoured Pass
Compaction alleviation Pass Dust and erosion control Pass
Non cropland: Revegetated 80% Pass Cropland: perennial forage Pass
Weeds present Pass Subsidence Pass

Comment: PA marker identified among native shrubs and grasses.

Corrective Action:

Date

Overall Final Reclamation Pass

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
------------------	-----------------	-------------------------	-----------------------	---------------	--------------------------	---------

S/U/V: Pass Corrective Date: Pass

Comment:

CA: