

Inspector Name: SCHURE, KYM

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

06/06/2012

Document Number:

663300159

Overall Inspection:

**Unsatisfactory****FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>265071</u>	<u>312317</u>		<u>SCHURE, KYM</u>

**Operator Information:**OGCC Operator Number: 17180 Name of Operator: CITATION OIL & GAS CORPAddress: 14077 CUTTEN RDCity: HOUSTON State: TX Zip: 77269**Contact Information:****Compliance Summary:**QtrQtr: NWNE Sec: 6 Twp: 9N Range: 52W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/01/2008	200194303	PR	PR	S			N
12/16/2002	200032470	PR	PR	U		P	N

**Inspector Comment:**

Shared batteryGear box leaking at pump jack, stuffing box leaking

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
265071	WELL	PR	11/13/2003	OW	075-09333	FLUHARTY 1	<input checked="" type="checkbox"/>

**Equipment:****Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
Crude Oil	WELLHEAD	<= 5 bbls	Remove or remediate stained soil	07/31/2012

Inspector Name: SCHURE, KYM

Crude Oil	Pump Jack	<= 5 bbls	Remove or remediate stained soil	07/31/2012
-----------	-----------	-----------	----------------------------------	------------

☐ Multiple Spills and Releases?

<b>Equipment:</b>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gathering Line	1	Satisfactory			
Pump Jack	1	Unsatisfactory	Oil stained soil at gear box	Remove or remediate	07/31/2012
Deadman # & Marked	4	Satisfactory			

<b>Venting:</b>		
Yes/No	Comment	

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 312317

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:****Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 265071 Type: WELL API Number: 075-09333 Status: PR Insp. Status: PR

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Inspector Name: SCHURE, KYM

Comment: <input style="width:700px" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
<b>Water Well:</b>			
		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
<b>Field Parameters:</b>			
<input style="width:300px" type="text"/>			
Sample Location: <input style="width:400px" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: _____	
Comment: <input style="width:750px" type="text"/>	
1003a. Debris removed? _____ CM _____	
CA _____	CA Date _____
Waste Material Onsite? _____ CM _____	
CA _____	CA Date _____
Unused or unneeded equipment onsite? _____ CM _____	
CA _____	CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____	
CA _____	CA Date _____
Guy line anchors removed? _____ CM _____	
CA _____	CA Date _____
Guy line anchors marked? _____ CM _____	
CA _____	CA Date _____
1003b. Area no longer in use? _____	
Production areas stabilized ? _____	
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	
Subsidence over on drill pit? _____	
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____	
Production areas have been stabilized? _____	
Segregated soils have been replaced? _____	
<b>RESTORATION AND REVEGETATION</b>	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____
Perennial forage re-established _____	

Inspector Name: SCHURE, KYM

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_