

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
06/29/2012

Document Number:
666900016

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>CHESSON, BOB</u>
	<u>329735</u>	<u>329735</u>		

Operator Information:

OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

Contact Information:

Compliance Summary:

QtrQtr: NWNW Sec: 29 Twp: 1N Range: 68W

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
249966	WELL	PR	01/03/2004	OG	123-17769	PRATT 'F' UNIT 1	<input checked="" type="checkbox"/>
419910	WELL	XX	10/21/2010		123-32376	PRATT 2-0-29	<input checked="" type="checkbox"/>
419911	WELL	XX	10/21/2010		123-32377	PRATT 0-2-29	<input checked="" type="checkbox"/>
419942	WELL	XX	10/21/2010		123-32387	PRATT 2-4-29	<input checked="" type="checkbox"/>
420033	WELL	XX	10/27/2010		123-32428	PRATT 21-29	<input checked="" type="checkbox"/>
420035	WELL	XX	10/27/2010		123-32430	PRATT 4-2-29	<input checked="" type="checkbox"/>
420037	WELL	XX	10/27/2010		123-32432	PRATT 12-29	<input checked="" type="checkbox"/>
420039	WELL	XX	10/27/2010		123-32434	PRATT 22-29	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>8</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>5</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>8</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: <u>3</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
		No signs (new location under construction)		06/15/2012

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action:

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	1	Satisfactory			06/15/2012
Emission Control Device	1	Satisfactory			06/15/2012
Horizontal Heated Separator	3	Satisfactory	not fenced.		06/15/2012

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	1	200 BBLS	PBV STEEL	,	
S/U/V: Satisfactory	Comment:				
Corrective Action:				Corrective Date:	06/15/2012

Paint

Condition	<input type="text"/>
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Corrective Action	Same cpntainment as crude tanks.			Corrective Date	06/08/2012
Comment					

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS	
CRUDE OIL	4	300 BBLS	STEEL AST	40.028000,-105.035460	
S/U/V: Satisfactory	Comment: New location (needs labling)				
Corrective Action:				Corrective Date:	

Paint

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal					
Corrective Action				Corrective Date	
Comment					

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 329735

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility				
Facility ID: <u>249966</u>	Type: <u>WELL</u>	API Number: <u>123-17769</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>419910</u>	Type: <u>WELL</u>	API Number: <u>123-32376</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>419911</u>	Type: <u>WELL</u>	API Number: <u>123-32377</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>419942</u>	Type: <u>WELL</u>	API Number: <u>123-32387</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>420033</u>	Type: <u>WELL</u>	API Number: <u>123-32428</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>420035</u>	Type: <u>WELL</u>	API Number: <u>123-32430</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>420037</u>	Type: <u>WELL</u>	API Number: <u>123-32432</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>420039</u>	Type: <u>WELL</u>	API Number: <u>123-32434</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: INDUSTRIAL

Comment:

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RESIDENTIAL _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

COGCC Comments		
Comment	User	Date
Location under expansion with new wells drilled and possibly completed. Work-over rig on location.	chessonr	06/29/2012