

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/06/2012

Document Number:

667600521

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>423813</u>	<u>327584</u>		<u>HICKEY, MIKE</u>

Operator Information:

OGCC Operator Number: 47120 Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Contact Information:

Contact Name	Phone	Email	Comment
Cocciolone, Ashley	720-929-6625	Ashley.Cocciolone@anadarko.com	
Avant, Paul	720-929-6457	Paul.Avant@anadarko.com	
Kilcrease, Keith	/24135	keith.kilcrease@anadarko.co	Production Superintendent

Compliance Summary:

QtrQtr: SESE Sec: 29 Twp: 1N Range: 67W

Inspector Comment:

New well inspection of API #05-123-33744, Howard #9-29. Site construction is under way.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
247097	WELL	PR	02/12/1998	GW	123-14894	UPRR 43 PAN AM L 2	<input checked="" type="checkbox"/>
423796	WELL	PR	03/05/2012	GW	123-33730	HOWARD 39-29	<input checked="" type="checkbox"/>
423801	WELL	PR	03/05/2012	GW	123-33734	HOWARD 23-29	<input checked="" type="checkbox"/>
423802	WELL	XX	06/24/2011		123-33735	HOWARD 37-29	<input checked="" type="checkbox"/>
423803	WELL	PR	03/05/2012	GW	123-33736	HOWARD 15-29	<input checked="" type="checkbox"/>
423808	WELL	PR	03/05/2012	GW	123-33739	HOWARD 24-29	<input checked="" type="checkbox"/>
423809	WELL	PR	02/16/2012	GW	123-33740	HOWARD 10-29	<input checked="" type="checkbox"/>
423810	WELL	PR	03/05/2012		123-33741	HOWARD 16-29	<input checked="" type="checkbox"/>
423813	WELL	PR	03/13/2012	GW	123-33744	HOWARD 9-29	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>9</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory			
BATTERY	Satisfactory			
WELLHEAD	Satisfactory	Signs for wellheads have not been placed, but are being placed presently.		

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK BATTERY	Satisfactory			
SEPARATOR	Satisfactory			
IGNITOR/COMBUST OR	Satisfactory	X3		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Compressor	1	Satisfactory			
Plunger Lift	9	Satisfactory			
Horizontal Heated Separator	3	Satisfactory			
Gas Meter Run	1	Satisfactory			
Emission Control Device	3	Satisfactory			
Bird Protectors	6	Satisfactory			

Inspector Name: HICKEY, MIKE

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS	,
S/U/V:	Satisfactory		Comment:	
Corrective Action:			Corrective Date:	

Paint

Condition	
-----------	--

Other (Content) _____

Other (Capacity) 210 Bbl. _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action				Corrective Date	
Comment					

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
CRUDE OIL	5	300 BBLS	STEEL AST	40.017180,104.906790
S/U/V:	Satisfactory		Comment:	
Corrective Action:			Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action				Corrective Date	
Comment					

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 327584

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:**

BMP Type

Comment

Material Handling and
Spill Prevention

Kerr McGee will build a 2 foot tall earthen berm along the entire Northeast side of the location along with the silt fence to keep sediment out of the ditch that is roughly 121 feet away.

Comment: _____**CA:** _____**Date:** _____**Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 247097 Type: WELL API Number: 123-14894 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Inspector Name: HICKEY, MIKE

Facility ID: 423796	Type: WELL	API Number: 123-33730	Status: PR	Insp. Status: PR
Producing Well				
Comment: <input style="width:90%" type="text"/>				

Facility ID: 423801	Type: WELL	API Number: 123-33734	Status: PR	Insp. Status: PR
Producing Well				
Comment: <input style="width:90%" type="text"/>				

Facility ID: 423802	Type: WELL	API Number: 123-33735	Status: XX	Insp. Status: PR
Producing Well				
Comment: <input style="width:90%" type="text"/>				

Facility ID: 423803	Type: WELL	API Number: 123-33736	Status: PR	Insp. Status: PR
Producing Well				
Comment: <input style="width:90%" type="text"/>				

Facility ID: 423808	Type: WELL	API Number: 123-33739	Status: PR	Insp. Status: PR
Producing Well				
Comment: <input style="width:90%" type="text"/>				

Facility ID: 423809	Type: WELL	API Number: 123-33740	Status: PR	Insp. Status: PR
Producing Well				
Comment: <input style="width:90%" type="text"/>				

Facility ID: 423810	Type: WELL	API Number: 123-33741	Status: PR	Insp. Status: PR
Producing Well				
Comment: <input style="width:90%" type="text"/>				

Facility ID: 423813	Type: WELL	API Number: 123-33744	Status: PR	Insp. Status: PR
Producing Well				
Comment: <input style="width:90%" type="text"/>				

Environmental				
Spills/Releases:				
Type of Spill: <input style="width:20%" type="text"/>	Description: <input style="width:40%" type="text"/>	Estimated Spill Volume: <input style="width:40%" type="text"/>		
Comment: <input style="width:90%" type="text"/>				
Corrective Action: <input style="width:80%" type="text"/>				Date: <input style="width:20%" type="text"/>
Reportable: <input style="width:20%" type="text"/>	GPS: Lat <input style="width:20%" type="text"/>	Long <input style="width:20%" type="text"/>		
Proximity to Surface Water: <input style="width:20%" type="text"/>	Depth to Ground Water: <input style="width:40%" type="text"/>			

Water Well:				
DWR Receipt Num: <input style="width:20%" type="text"/>	Owner Name: <input style="width:30%" type="text"/>	GPS : <input style="width:20%" type="text"/>	Lat <input style="width:10%" type="text"/> Long <input style="width:10%" type="text"/>	

Field Parameters:
Sample Location: <input style="width:90%" type="text"/>

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IMPROVED PASTURE

Comment: _____

1003a. Debris removed? _____ CM _____
 CA _____ CA Date _____
 Waste Material Onsite? _____ CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? _____ CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IMPROVED PASTURE

Reminder: _____

Inspector Name: HICKEY, MIKE

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
Debris removed _____ No disturbance /Location never built _____
Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
Compaction alleviation _____ Dust and erosion control _____
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
Weeds present _____ Subsidence _____

Comment:

Corrective Action:

Date

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
------------------	-----------------	-------------------------	-----------------------	---------------	--------------------------	---------

S/U/V: _____ Corrective Date: _____

Comment:

CA: