

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/18/2012

Document Number:

663400630

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>225509</u>	<u>313821</u>		<u>EDELEN, RANDY</u>

**Operator Information:**

OGCC Operator Number: 18600 Name of Operator: COLORADO INTERSTATE GAS COMPANY LLC

Address: P O BOX 1087

City: COLORADO State: CO Zip: 80944

**Contact Information:**

Contact Name	Phone	Email	Comment
ONYSKIW, DENISE		denise.onyskiw@state.co.us	
Livley, Kevin	970-867-4243	Kevin.Lively@EIPaso.com	
Jarrell, Greg	(970) 370-3209	Greg_Jarrel@kindermorgan.com	

**Compliance Summary:**

QtrQtr: NESW Sec: 25 Twp: 3N Range: 58W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/23/2012	665400066	IJ	IJ	S			N
07/20/2011	200315515	RT	AC	S			N
06/23/2010	200258462	RT	AC	S			N
04/21/2010	200243815	BH	SI	S			N
10/15/2009	200220307	BH	SI	S			N
10/15/2009	200220781	BH	SI	S			N
08/13/2009	200216522	RT	AC	S			N
04/09/2009	200208647	BH	SI	S			N
04/09/2009	200208646	BH	SI	S			N
10/16/2008	200197807	RT	AC	S			N
03/20/2007	200108387	MI	AC	S		P	N
05/30/2006	200091304	RT	AC	S		P	N
08/30/2005	200076013	RT	AC	S		P	N
08/31/2004	200059169	RT	SI	S		P	N
05/15/2003	200038873	RT	AC	S		P	N
04/10/2002	200026055	MI	AC	S		P	N
07/27/2001	200018301	RT	AC	S		P	N
05/02/2000	200006715	RT	AC	S	P	P	N

**Inspector Comment:**

Routine UIC

Inspector Name: EDELEN, RANDY

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
225509	WELL	IJ	01/19/2012	DSPW	087-05922	FORT MORGAN UNIT 5-WD	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: \_\_\_\_\_

Comment: Previously verified

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
	Satisfactory			

**Equipment:**

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Flow Line	1	Satisfactory			

**Venting:**

Yes/No	Comment
NO	

**Flaring:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 313821

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:****Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 225509 Type: WELL API Number: 087-05922 Status: IJ Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_

Maximum Injection Pressure: \_\_\_\_\_

**UIC Routine**

Inj./Tube: Pressure or inches of Hg 0 psig Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND

TC: Pressure or inches of Hg 19.1 psig Previous Test Pressure \_\_\_\_\_ Last MIT: 01/17/2012

Brhd: Pressure or inches of Hg 49.3 psig Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: Part of Fort Morgan Storage field

Method of Injection: \_\_\_\_\_

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors removed? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_  
 Guy line anchors marked? Pass CM \_\_\_\_\_  
 CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? Pass  
 1003c. Compacted areas have been cross ripped? Pass  
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass  
 Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established Pass

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? P

Comment: \_\_\_\_\_

Overall Interim Reclamation Pass

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Inspector Name: EDELEN, RANDY

S/U/V: Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_