
WPX ENERGY ROCKY MOUNTAIN LLC-EBUS

**SG 413-27
SOUTH GRAND VALLEY
Garfield County , Colorado**

Cement Surface Casing
21-May-2012

Post Job Report

The Road to Excellence Starts with Safety

Sold To #: 300721		Ship To #: 300721		Quote #:		Sales Order #: 9518608	
Customer: WPX ENERGY ROCKY MOUNTAIN LLC-EBUS				Customer Rep: Moore, Frank			
Well Name: SG			Well #: 413-27			API/UWI #:	
Field: SOUTH GRAND VALLEY		City (SAP): TULSA		County/Parish: Garfield		State: Colorado	
Contractor: NABORS 573			Rig/Platform Name/Num: NABORS 573				
Job Purpose: Cement Surface Casing							
Well Type: Development Well				Job Type: Cement Surface Casing			
Sales Person: MAYO, MARK				Srvc Supervisor: SLAUGHTER, JESSE			
MBU ID Emp #: 454315							

Job Personnel

HES Emp Name	Exp Hrs	Emp #	HES Emp Name	Exp Hrs	Emp #	HES Emp Name	Exp Hrs	Emp #
GOWEN, WESLEY M	6.5	496205	KUKUS, CARLTON Dean	6.5	458577	SLAUGHTER, JESSE Dean	6.5	454315

Equipment

HES Unit #	Distance-1 way						
10867423	60 mile	11259881	60 mile	11560046	60 mile	11562538	60 mile
11808833	60 mile						

Job Hours

Date	On Location Hours	Operating Hours	Date	On Location Hours	Operating Hours	Date	On Location Hours	Operating Hours
5-21-2012	6.5	3						
TOTAL			<i>Total is the sum of each column separately</i>					

Job

Job Times

Formation Name	Date	Time	Time Zone
Formation Depth (MD) Top Bottom	Called Out	21 - May - 2012	05:00 MST
Form Type BHST	On Location	21 - May - 2012	08:00 MST
Job depth MD 1230. ft Job Depth TVD 1230. ft	Job Started	21 - May - 2012	11:33 MST
Water Depth Wk Ht Above Floor 9. ft	Job Completed	21 - May - 2012	12:29 MST
Perforation Depth (MD) From To	Departed Loc	21 - May - 2012	14:30 MST

Well Data

Description	New / Used	Max pressure psig	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
-------------	------------	-------------------	---------	-------	---------------	--------	-------	-----------	--------------	------------	---------------

Sales/Rental/3rd Party (HES)

Description	Qty	Qty uom	Depth	Supplier
PLUG,CMTG, TOP, 9 5/8, HWE, 8.16 MIN/9.06 MA	1	EA		

Tools and Accessories

Type	Size	Qty	Make	Depth	Type	Size	Qty	Make	Depth	Type	Size	Qty	Make
Guide Shoe					Packer					Top Plug	9.625	1	HES
Float Shoe					Bridge Plug					Bottom Plug			
Float Collar					Retainer					SSR plug set			
Insert Float										Plug Container	9.625	1	HES
Stage Tool										Centralizers			

Miscellaneous Materials

Gelling Agt	Conc	Surfactant	Conc	Acid Type	Qty	Conc %
Treatment Fld	Conc	Inhibitor	Conc	Sand Type	Size	Qty

Fluid Data

Stage/Plug #: 1										
Fluid #	Stage Type	Fluid Name	Qty	Qty uom	Mixing Density lbm/gal	Yield ft ³ /sk	Mix Fluid Gal/sk	Rate bbl/min	Total Mix Fluid Gal/sk	

Stage/Plug #: 1

Stage/Plug #: 1									
Fluid #	Stage Type	Fluid Name	Qty	Qty uom	Mixing Density lbm/gal	Yield ft ³ /sk	Mix Fluid Gal/sk	Rate bbl/min	Total Mix Fluid Gal/sk
1	Fresh Water	FRESH WATER	20.00	bbl	8.33	.0	.0	4	
2	VersaCem Lead	VERSACEM (TM) SYSTEM (452010)	175.0	sacks	12.3	2.38	13.77	8	13.77
	13.77 Gal	FRESH WATER							
3	VersaCem Tail	VERSACEM (TM) SYSTEM (452010)	160.0	sacks	12.8	2.11	11.75	8	11.75
	11.75 Gal	FRESH WATER							
4	Displacement Fluid	FRESH WATER	93.3	bbl	8.34	.0	.0	10	
Calculated Values		Pressures		Volumes					
Displacement	93.3	Shut In: Instant		Lost Returns	NO	Cement Slurry	134	Pad	
Top Of Cement	SURFACE	5 Min		Cement Returns	30	Actual Displacement	93.3	Treatment	
Frac Gradient		15 Min		Spacers	20	Load and Breakdown		Total Job	248
Rates									
Circulating		Mixing	8	Displacement	10	Avg. Job	9		
Cement Left In Pipe	Amount	0 ft	Reason	Shoe Joint					
Frac Ring # 1 @	ID	Frac ring # 2 @	ID	Frac Ring # 3 @	ID	Frac Ring # 4 @	ID		
The Information Stated Herein Is Correct				Customer Representative Signature					

The Road to Excellence Starts with Safety


Sold To #: 300721		Ship To #: 300721		Quote #:		Sales Order #: 9518608	
Customer: WPX ENERGY ROCKY MOUNTAIN LLC-EBUS				Customer Rep: Moore, Frank			
Well Name: SG			Well #: 413-27		API/UWI #:		
Field: SOUTH GRAND VALLEY		City (SAP): TULSA		County/Parish: Garfield		State: Colorado	
Legal Description:							
Lat:				Long:			
Contractor: NABORS 573			Rig/Platform Name/Num: NABORS 573				
Job Purpose: Cement Surface Casing					Ticket Amount:		
Well Type: Development Well			Job Type: Cement Surface Casing				
Sales Person: MAYO, MARK			Srvc Supervisor: SLAUGHTER, JESSE		MBU ID Emp #: 454315		

Activity Description	Date/Time	Cht #	Rate bbl/min	Volume bbl		Pressure psig		Comments
				Stage	Total	Tubing	Casing	
Call Out	05/21/2012 05:00							TD 1234 FT, TP 1230 FT, SHOE 44.49 FT. CSG 9 5/8 IN 32.3 LB/FT, HOLE 13 1/2 IN, MUD WT 10.9 PPG
Pre-Convoy Safety Meeting	05/21/2012 06:50							WITH ALL HES PERSONNEL
Crew Leave Yard	05/21/2012 07:00							
Arrive At Loc	05/21/2012 08:00							RIG WAS RUNNING CASING UPON HES ARRIVAL
Assessment Of Location Safety Meeting	05/21/2012 10:00							WITH ALL HES PERSONNEL
Other	05/21/2012 10:10							SPOT EQUIPMENT
Pre-Rig Up Safety Meeting	05/21/2012 10:20							WITH ALL HES PERSONNEL
Rig-Up Equipment	05/21/2012 10:30							
Pre-Job Safety Meeting	05/21/2012 11:20							WITH ALL PERSONNEL ON LOCATION
Start Job	05/21/2012 11:33							
Other	05/21/2012 11:33		2	2			47.0	FILL LINES WITH FRESH WATER
Test Lines	05/21/2012 11:35							TESTED LINES TO 3113 PSI PRESSURE HOLDING
Pump Spacer 1	05/21/2012 11:41		4	20			108.0	FRESH WATER
Pump Lead Cement	05/21/2012 11:50		8	74.2			305.0	175 SKS AT 12.3 PPG, 2.38 FT3/SK, 13.75 GAL/SK

Activity Description	Date/Time	Cht #	Rate bbl/min	Volume bbl		Pressure psig		Comments
				Stage	Total	Tubing	Casing	
Pump Tail Cement	05/21/2012 12:03		8	60.1			320.0	160 SKS AT 12.8 PPG, 2.11 FT3/SK, 11.75 GAL/SK
Shutdown	05/21/2012 12:11							
Drop Top Plug	05/21/2012 12:12							PLUG LAUNCHED
Pump Displacement	05/21/2012 12:14		10	83.3			570.0	FRESH WATER
Slow Rate	05/21/2012 12:23		2	10			245.0	SLOW RATE 10 BBLs PRIOR TO CALCULATED DISPLACEMENT
Bump Plug	05/21/2012 12:27		2		93.3		665.0	PLUG BUMPED
Check Floats	05/21/2012 12:28							FLOATS HOLDING. HES RETURNED 1/2 BBL H2O TO PUMP
End Job	05/21/2012 12:29							PIPE WAS STATIC THROUGHOUT JOB, GOOD CIRCULATION THROUGHOUT JOB. HES RETURNED 30 BBL CEMENT TO SURFACE
Pre-Rig Down Safety Meeting	05/21/2012 12:35							WITH ALL HES PERSONNEL
Rig-Down Equipment	05/21/2012 12:45							
Pre-Convoy Safety Meeting	05/21/2012 14:20							WITH ALL HES PERSONNEL
Crew Leave Location	05/21/2012 14:30							
Comment	05/21/2012 14:31							THANK YOU FOR USING HALLIBURTON CEMENT DEPARTMENT. JESSE SLAUGHTER AND CREW.

WILLIAMS SG 413-27

9 5/8 SURFACE




Local Event Log								
1	START JOB	11:33:11	2	PRIME LINES	11:33:18	3	TEST LINES	11:35:24
4	PUMP H2O SPACER	11:41:45	5	PUMP LEAD CEMENT	11:50:54	6	PUMP TAIL CEMENT	12:03:43
7	SHUTDOWN	12:11:23	8	DROP TOP PLUG	12:12:53	9	PUMP DISPLACEMENT	12:14:28
10	SLOW RATE	12:23:20	11	BUMP PLUG	12:27:13	12	CHECK FLOATS	12:28:36
13	END JOB	12:29:10						

Customer: WILLIAMS	Job Date: 21-May-2012	Sales Order #: 9518608
Well Description: SG 413-27	Job Type: SURFACE	ADC Used: YES
Customer Rep: FRANK MOORE	Cement Supervisor: JESSE SLAUGHTER	Elite #5: WESLEY GOWEN

WILLIAMS SG 413-27

9 5/8 SURFACE



Customer: WILLIAMS	Job Date: 21-May-2012	Sales Order #: 9518608
Well Description: SG 413-27	Job Type: SURFACE	ADC Used: YES
Customer Rep: FRANK MOORE	Cement Supervisor: JESSE SLAUGHTER	Elite #5: WESLEY GOWEN

HALLIBURTON

Water Analysis Report

Company: WILLIAMS PRODUCTION

Date: 5/21/2012

Submitted by: JESSE SLAUGHTER

Date Rec.: _____

Attention: LAB

S.O.# 9518608

Lease SG

Job Type: SURFACE

Well # 413-27

Specific Gravity	<i>MAX</i>	1
pH	<i>8</i>	6
Potassium (K)	<i>5000</i>	250 Mg / L
Calcium (Ca)	<i>500</i>	120 Mg / L
Iron (FE2)	<i>300</i>	0 Mg / L
Chlorides (Cl)	<i>3000</i>	0 Mg / L
Sulfates (SO ₄)	<i>1500</i>	UNDER 200 Mg / L
Chlorine (Cl ₂)		0 Mg / L
Temp	<i>40-80</i>	55 Deg
Total Dissolved Solids		200 Mg / L

Respectfully: JESSE SLAUGHTER

Title: CEMENTING SUPERVISOR

Location: Grand Junction, CO

NOTICE:

This report is limited to the described sample tested. Any person using or relying on this report agrees that Halliburton shall not be liable for any loss or damage whether due to act or omission resulting from such report or its

Sales Order #: 9518608	Line Item: 10	Survey Conducted Date: 5/21/2012
Customer: WPX ENERGY ROCKY MOUNTAIN LLC-EBUS		Job Type (BOM): CMT SURFACE CASING BOM
Customer Representative: FRANK MOORE		API / UWI: (leave blank if unknown) AFEYCBFPO4JSVMZRAAA
Well Name: SG		Well Number: 413-27
Well Type: Development Well	Well Country: United States of America	
H2S Present:	Well State: Colorado	Well County: Garfield

Dear Customer,

We hope that you were satisfied with the service quality of this job performed by Halliburton. It is the aim of our management and service personnel to deliver equipment and service of a standard unmatched in the service sector of the energy industry.

Please take the time to let us know if our performance met with your satisfaction. Please be as critical as possible to ensure we constantly improve our service. Your comments are of great value to us and are intended for the exclusive use of Halliburton.

CUSTOMER SATISFACTION SURVEY

CATEGORY	CUSTOMER SATISFACTION RESPONSE	
Survey Conducted Date	The date the survey was conducted	5/21/2012
Survey Interviewer	The survey interviewer is the person who initiated the survey.	JESSE SLAUGHTER (HB21762)
Customer Participation	Did the customer participate in this survey? (Y/N)	Yes
Customer Representative	Enter the Customer representative name	FRANK MOORE
HSE	Was our HSE performance satisfactory? Circle Y or N	Yes
Equipment	Were you satisfied with our Equipment? Circle Y or N	Yes
Personnel	Were you satisfied with our people? Circle Y or N	Yes
Customer Comment	Customer's Comment	

CUSTOMER SIGNATURE

Sales Order #: 9518608	Line Item: 10	Survey Conducted Date: 5/21/2012
Customer: WPX ENERGY ROCKY MOUNTAIN LLC-EBUS		Job Type (BOM): CMT SURFACE CASING BOM
Customer Representative: FRANK MOORE		API / UWI: (leave blank if unknown) AFEYCBFPO4JSVMZRAAA
Well Name: SG		Well Number: 413-27
Well Type: Development Well	Well Country: United States of America	
H2S Present:	Well State: Colorado	Well County: Garfield

KEY PERFORMANCE INDICATORS

General	
Survey Conducted Date	5/21/2012
The date the survey was conducted	

Cementing KPI Survey	
Type of Job	0
Select the type of job. (Cementing or Non-Cementing)	
Select the Maximum Deviation range for this Job	Vertical
What is the highest deviation for the job you just completed? This may not be the maximum well deviation.	
Total Operating Time (hours)	3
Total Operating Hours Including Rig-up, Pumping, Rig-down. Enter in decimal format.	
HSE Incident, Accident, Injury	No
HSE Incident, Accident, Injury. This should be recordable incidents only.	
Was the job purpose achieved?	Yes
Was the job delivered correctly as per customer agreed design?	
Operating Hours (Pumping Hours)	1
Total number of hours pumping fluid on this job. Enter in decimal format.	
Customer Non-Productive Rig Time (hrs)	0
Lost time due to Halliburton in the start, execution, or completion of an ordered service or product, or delays in a follow-on service. Enter in decimal format. 0 if none.	
Type of Rig Classification Job Was Performed	Drilling Rig (Portable)
Type Of Rig (classification) Job Was Performed On	
Number Of JSAs Performed	6
Number Of Jsas Performed	
Number of Unplanned Shutdowns	0
Unplanned shutdown is when injection stops for any period of time.	
Was this a Primary Cement Job (Yes / No)	Yes

Sales Order #: 9518608	Line Item: 10	Survey Conducted Date: 5/21/2012
Customer: WPX ENERGY ROCKY MOUNTAIN LLC-EBUS		Job Type (BOM): CMT SURFACE CASING BOM
Customer Representative: FRANK MOORE		API / UWI: (leave blank if unknown) AFEYCBFPO4JSVMZRAAA
Well Name: SG		Well Number: 413-27
Well Type: Development Well	Well Country: United States of America	
H2S Present:	Well State: Colorado	Well County: Garfield

Primary Cement Job= Casing job, Liner job, or Tie-back job.	
Did We Run Wiper Plugs? Did We Run Top And Bottom Casing Wiper Plugs?	Top
Mixing Density of Job Stayed in Designed Density Range (0-100%) Density Range defined as +/- .20 ppg. Calculation: Total BBLs cement mixed at designed density divided by total BBLs of cement multiplied by 100	95
Was Automated Density Control Used? Was Automated Density Control (ADC) Used ?	Yes
Pump Rate (percent) of Job Stayed At Designed Pump Rate Pump Rate range defined as +/- 1bbl/min. Calculation: Total BBLs of fluid pumped at the designed rate divided by Total BBLs of fluid pumped, multiplied by 100	98
Nbr of Remedial Sqz Jobs Rqd - Competition Number Of Remedial Squeeze Jobs Required After Primary Job Performed By Competition	0
Nbr of Remedial Plug Jobs Rqd - HES Number Of Remedial Plug Jobs Needed After Primary Plug Pumped By HES	0
Nbr of Remedial Sqz Jobs Rqd - HES Number Of Remedial Squeeze Jobs Required After Primary Job Performed By HES	0