

FORM
5Rev
02/08

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400277490

Date Received:

04/30/2012

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type ☒ Final completion ☐ Preliminary completion

1. OGCC Operator Number: 10311

4. Contact Name: Craig Rasmuson

2. Name of Operator: SYNERGY RESOURCES CORPORATION

Phone: (970) 737-1073

3. Address: 20203 HIGHWAY 60

Fax: (970) 737-1045

City: PLATTEVILLE State: CO Zip: 80651

5. API Number 05-123-33827-00

6. County: WELD

7. Well Name: SRC Haythorn

Well Number: 32-36D

8. Location: QtrQtr: NENE Section: 36 Township: 7N Range: 66W Meridian: 6

Footage at surface: Distance: 816 feet Direction: FNL Distance: 1231 feet Direction: FEL

As Drilled Latitude: 40.536900 As Drilled Longitude: -104.720277

GPS Data:

Data of Measurement: 10/25/2011 PDOP Reading: 2.2 GPS Instrument Operator's Name: B. Albrandt

** If directional footage at Top of Prod. Zone Dist.: 2085 feet. Direction: FNL Dist.: 2202 feet. Direction: FEL

Sec: 36 Twp: 7N Rng: 66W

** If directional footage at Bottom Hole Dist.: 2084 feet. Direction: FNL Dist.: 2203 feet. Direction: FEL

Sec: 36 Twp: 7N Rng: 66W

9. Field Name: EATON

10. Field Number: 19350

11. Federal, Indian or State Lease Number:

12. Spud Date: (when the 1st bit hit the dirt) 10/08/2011 13. Date TD: 10/12/2011 14. Date Casing Set or D&A: 10/13/2011

15. Well Classification:

☐ Dry ☐ Oil ☒ Gas/Coalbed ☐ Disposal ☐ Stratigraphic ☐ Enhanced Recovery ☐ Storage ☐ Observation

16. Total Depth MD 7700 TVD** 7462 17 Plug Back Total Depth MD 7650 TVD** 7412

18. Elevations GR 4853 KB 4865

One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:

Cement Bond VDL Gamma Ray CCL
High Resolution Compensated Density Compensated Neutron

20. Casing, Liner and Cement:

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
SURF	12+1/4	8+5/8	24	0	687	430	0	687	CALC
1ST	7+7/8	4+1/2	11.6	0	7,695	590	3,374	7,695	CBL

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____					
Method used	String	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom
Details of work:					

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES					
FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
GREELEY SAND	2,956		<input type="checkbox"/>	<input type="checkbox"/>	
PARKMAN	3,904		<input type="checkbox"/>	<input type="checkbox"/>	
SUSSEX	4,734		<input type="checkbox"/>	<input type="checkbox"/>	
SHANNON	5,239		<input type="checkbox"/>	<input type="checkbox"/>	
NIOBRARA	7,244		<input type="checkbox"/>	<input type="checkbox"/>	
FORT HAYS	7,494		<input type="checkbox"/>	<input type="checkbox"/>	
CODELL	7,529		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

Please Cc: crasmuson@syrinfo.com with future correspondence for this form.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Kori Thoren

Title: Land Assistant Date: 4/30/2012 Email: kthoren@syrinfo.com

Attachment Check List

Att Doc Num	Document Name	attached ?			
<u>Attachment Checklist</u>					
400277516	CMT Summary *	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
	Core Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
400277521	Directional Survey **	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
	DST Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Logs	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
	Other	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
<u>Other Attachments</u>					
400277490	FORM 5 SUBMITTED	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
400277522	DIRECTIONAL DATA	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
400278271	LAS-	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>

General Comments

User Group	Comment	Comment Date
Permit	Off hold. Corrected SHL, top of production zone, and BHL per operator.	3/1/2012 1:49:52 PM
Permit	On Hold. SHL does not match SHL on APD	7/25/2012 2:01:09 PM

Total: 2 comment(s)