

Inspector Name: SCHURE, KYM

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

09/22/2012

Document Number:

663300599

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|---------------|---------------|---------------|--------------------|
| Location Identifier | Facility ID | Loc ID | Tracking Type | Inspector Name: |
| | <u>280731</u> | <u>336912</u> | | <u>SCHURE, KYM</u> |

Operator Information:OGCC Operator Number: 66190 Name of Operator: OMIMEX PETROLEUM INCAddress: 7950 JOHN T WHITE ROADCity: FORT WORTHState: TXZip: 76120**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|-------------------------------|---------|
| Fisher, Jeremy | 970-854-4733 | Jeremy_Fisher@omimexgroup.com | |

Compliance Summary:Qtr/Qtr: SWSW Sec: 10 Twp: 5N Range: 45W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 10/22/2007 | 200121216 | PR | PR | S | | | N |
| 04/19/2007 | 200110407 | PR | PR | S | | P | N |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------------------------------|
| 280731 | WELL | PR | 12/27/2005 | GW | 125-09567 | FERGUSON 13-10-5-45 | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|-----------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Motors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

LocationEmergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

| Fencing/: | | | | |
|------------------|-----------------------------|--------------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| PUMP JACK | Satisfactory | Steel panels | | |

| Equipment: | | | | | |
|-------------------|---|-----------------------------|---|---------------------|------------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Pump Jack | 1 | Unsatisfactory | Containment under chemical additive tank. | Install containment | 11/01/2012 |
| Gas Meter Run | 1 | Satisfactory | | | |

| | | |
|------------------------|---------|--|
| <u>Venting:</u> | | |
| Yes/No | Comment | |
| | | |

| Flaring: | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 336912

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

| | | | |
|--------------|---------|------------|---------|
| Erosion BMPs | Present | Other BMPs | Present |
| | | | |

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 280731 Type: WELL API Number: 125-09567 Status: PR Insp. Status: PR

Producing Well

Comment: Gas well located in rolling hills/grassland. Pump Jack, P/W collected-injected, Gas meter run. Electric motor on PJ.

Environmental**Spills/Releases:**

Inspector Name: SCHURE, KYM

| | | |
|--|------------------------------|-------------------------------|
| Type of Spill: _____ | Description: _____ | Estimated Spill Volume: _____ |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | | |
| Corrective Action: _____ | | Date: _____ |
| Reportable: _____ | GPS: Lat _____ | Long _____ |
| Proximity to Surface Water: _____ | Depth to Ground Water: _____ | |

| | | | |
|------------------------|-------------------|-------------|------------|
| Water Well: | | Lat _____ | Long _____ |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ | |

Field Parameters:

Sample Location: _____

| |
|---|
| Emission Control Burner (ECB): _____ |
| Comment: _____ |
| Pilot: _____ Wildlife Protection Devices (fired vessels): _____ |

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

| | | | | | | | | |
|--------|---|-------|----|-------|----|-------|---------|-------|
| 1003a. | Debris removed? | Pass | CM | _____ | CA | _____ | CA Date | _____ |
| | Waste Material Onsite? | Pass | CM | _____ | CA | _____ | CA Date | _____ |
| | Unused or unneeded equipment onsite? | Pass | CM | _____ | CA | _____ | CA Date | _____ |
| | Pit, cellars, rat holes and other bores closed? | Pass | CM | _____ | CA | _____ | CA Date | _____ |
| | Guy line anchors removed? | _____ | CM | _____ | CA | _____ | CA Date | _____ |
| | Guy line anchors marked? | _____ | CM | _____ | CA | _____ | CA Date | _____ |

1003b. Area no longer in use? In Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? In

1003d. Drilling pit closed? Pass Subsidence over on drill pit? In

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? Pass Segregated soils have been replaced? In

RESTORATION AND REVEGETATION

Cropland

Inspector Name: SCHURE, KYM

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ In _____

Recontoured _____ In _____

80% Revegetation _____ In _____

1003 f. Weeds Noxious weeds? _____ I _____

Comment: _____

Overall Interim Reclamation _____ Pass _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads _____ Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: Gas well located in rolling hills/grassland. Roads are subject to erosion from runoff, generally sandy roads with sufficient grade to washout at turns. Adequately maintained' some ruts.

CA: _____