



Andrews, David

045-15489

From: Jeremy Rose [jrose@magnaes.com]
Sent: Saturday, September 22, 2012 4:50 PM
To: Dave Rebol (daverebol@hotmail.com); harlanhodge@hotmail.com; steven.vencill@encana.com; Kathy highberger (dkama@kci.net)
Cc: aronrt@hotmail.com; nortonjr69@gmail.com; Longworth, Mike; Andrews, David
Subject: Daily Report for Rig # 8 (2)

Follow Up Flag: Follow up
Flag Status: Flagged

DATE: 9/22/2012

OPERATOR: EnCana Oil and Gas
WELL NAME: N. Parachute EF07A-20 C29 595
COUNTY: Garfield, Colorado

11:00-12:30 MIRU. Spot in cement equipment.
12:30-2:00 Trip in hole and tag with joint 89 at 2722'. Shoe is at 2821'. BLM (Dave Andrews) approved us to proceed with original procedure.
2:00- 3:00 Pump 40 sacks (105') of cement into 9-5/8" casing at 2720'. Clean up cement equipment.
3:00-4:00 Trip out of hole with 10 joints (310') and secure well site. Shut down for night.
4:00-5:00 Travel to Parachute, Colorado.

All cement pumped was 15.8# Class "G" Neat with a yield of 1.15

Tool Pusher: Jeremy Rose
Work Over: Magna Energy Services Rig # 8
Cement Con. Magna Energy Services
Cement Sup. Jeremy Rose
Operations Sup. Steve Vencill
BLM Representative: Mike Longworth