

Inspector Name: QUINT, CRAIG

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

09/25/2012

Document Number:

663901732

Overall Inspection:

**Unsatisfactory****FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>415837</u>	<u>415684</u>		<u>QUINT, CRAIG</u>

**Operator Information:**

OGCC Operator Number: 10159 Name of Operator: ROSETTA RESOURCES OPERATING LP

Address: 717 TEXAS STE 2800

City: HOUSTON State: TX Zip: 77002

**Contact Information:**

Contact Name	Phone	Email	Comment
LEONARD, MIKE		mike.leonard@state.co.us	
Hildreth, Shawn	713-335-4104	shawn.hildreth@rosettaresources.com	Lead Regulatory Analyst

**Compliance Summary:**

QtrQtr: SENE Sec: 11 Twp: 2S Range: 45W

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
415837	WELL	AL	04/09/2012		125-11752	BOWMAN 11-08	<input checked="" type="checkbox"/>

**Equipment:****Location Inventory**

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: <u>1</u>	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>1</u>
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: <u>1</u>
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number: (S/U/V) \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory	LOCATION IS FENCED WITH WIRE.		

<b>Venting:</b>		
Yes/No	Comment	

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 415684

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:****Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 415837 Type: WELL API Number: 125-11752 Status: AL Insp. Status: DA

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Inspector Name: QUINT, CRAIG

Comment: <input style="width:700px" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
<b>Water Well:</b>			
		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
<b>Field Parameters:</b>			
<input style="width:300px" type="text"/>			
Sample Location: <input style="width:400px" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

**Reclamation - Storm Water - Pit**

<b>Interim Reclamation:</b>			
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____	
Land Use: IMPROVED PASTURE			
Comment: <input style="width:750px" type="text"/>			
1003a.	Debris removed? _____ CM _____		
	CA _____	CA Date _____	
	Waste Material Onsite? _____ CM _____		
	CA _____	CA Date _____	
	Unused or unneeded equipment onsite? _____ CM _____		
	CA _____	CA Date _____	
	Pit, cellars, rat holes and other bores closed? _____ CM _____		
	CA _____	CA Date _____	
	Guy line anchors removed? _____ CM _____		
	CA _____	CA Date _____	
	Guy line anchors marked? _____ CM _____		
	CA _____	CA Date _____	
1003b.	Area no longer in use? _____		Production areas stabilized ? _____
1003c.	Compacted areas have been cross ripped? _____		
1003d.	Drilling pit closed? _____		Subsidence over on drill pit? _____
	Cuttings management: _____		
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____		
	Production areas have been stabilized? _____		Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION			
<u>Cropland</u>			
	Top soil replaced _____	Recontoured _____	Perennial forage re-established _____

Inspector Name: QUINT, CRAIG

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: IMPROVED PASTURE

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured Pass

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% In

Cropland: perennial forage \_\_\_\_\_

Weeds present Fail

Subsidence Pass

Comment: LOCATION IS CLEAN, CONTOURED AND COVERED WITH WEEDS AND GRASS, LOCATION IS FENCED WITH WIRE.

Corrective Action: CONTROL WEEDS, REMOVE FENCE WHEN ADEQUATE GRASS COVERAGE HAS BEEN ACHIEVED. MAY NEED ONE MORE GROWING SEASON.

Date **09/25/2013**

Overall Final Reclamation

In Process

Multi-Well Location



**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_