



**DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT**  
1555 North 17<sup>th</sup> Avenue  
Greeley, CO 80631



**Public Health**  
Prevent. Promote. Protect

Web: [www.weldhealth.org](http://www.weldhealth.org)

**Health Administration  
Vital Records**  
Tele: 970.304.6410  
Fax: 970.304.6412

**Public Health & Clinical  
Services**  
Tele: 970.304.6420  
Fax: 970.304.6416

**Environmental Health  
Services**  
Tele: 970.304.6415  
Fax: 970.304.6411

**Communication,  
Education & Planning**  
Tele: 970.304.6470  
Fax: 970.304.6452

**Emergency Preparedness  
& Response**  
Tele: 970.304.6420  
Fax: 970.304.6469

*Our vision: Together with the communities we serve, we are working to make Weld County the healthiest place to live, learn, work and play.*

October 19, 2012

High Sierra Water Services, LLC  
Attn: Daniel Garcia  
8207 W. 20<sup>th</sup> Street, Suite B  
Greeley, Colorado 80634

Subject: High Sierra Water Services, LLC - C1 Facility (SWD 1-8), 2<sup>nd</sup> Semi-annual Inspection 2012

Dear Mr. Garcia:

On October 16, 2012, the Weld County Department of Public Health and Environment conducted a routine inspection of High Sierra Water Services, LLC - C1 Class II Injection Disposal Facility, located at 25849 Weld County Road 46, Weld County, Colorado. The purpose of the inspection was to assess the facility's compliance with the Approved Site Specific Development Plan and the 3<sup>rd</sup> Amended Use by Special Review Permit Number 996 (3<sup>rd</sup> AmUSR-996) and applicable Weld County Code.

Based on the inspection, the facility was in substantial compliance with 3AmUSR-996. A copy of the inspection form is attached. If you have any questions regarding this inspection, please contact me at 304-6415, extension 2219.

Sincerely,

Troy E. Swain  
Waste Program Coordinator  
Environmental Health Services

cc: Denise Onyskiw, COGCC, 1120 Lincoln St., Ste. 801, Denver, CO 80203 (via e-mail)

# INJECTION WELL INSPECTION REPORT CHECKLIST

FACILITY OWNER/OPERATOR: High Sierra Water Services, LLC

FACILITY NAME: C-1  
SWD 1-8A, 1-8B

FACILITY ID: 1591398159264 USR: 3Am USR-996  
65-123-23038  
65-123-99536

DATE: 10-16-2012 INSPECTION: Q/SA

WELL CLASS: III

CONTACT PERSON: Dan Garcia

PHONE: 970-284-5031

ADDRESS: 8207 W. 20th St. Ste B  
Greeley CO 80634

(Facility)  
970-356-5560  
970-397-9156 (C)

FACILITY LOCATION: 25849 CR 46 Kersey CO 80644

TRUCK DELIVERIES/DAY~ 65-75 Ave BARRELS INJECTED/DAY~ 9000 Ave  
(80-100 approx limit)  
by USR

INJECTION PRESSURE: 2640 psi (LIMIT 3200 psi).  
1500 1510

SOLIDS/SEDIMENT DISPOSAL NAME: CSI

PETROLEUM CONTAMINATED SOILS: no

ON-SITE STORAGE: Y/N

CONDITION OF CONCRETE RECEIVING PAD: OK

LEAK DETECTION SYSTEM MONITORING: Y/N

FREQ/RECORDS: 1/month

GROUNDWATER MONITORING WELL CONDITION: OK

REPORTS: Y/N

CHEMICALS STORED: Y/N

EMERGENCY RELEASES: Y/N

ISDS: Y/N VAULT

ENVIRONMENTAL SPECIALIST: Thuy Swain

PERSONS PRESENT AT TIME OF INSPECTION: Victor Vieyra, Dan Garcia, Monte

CURRENT CONDITIONS/COMMENTS:

C1A(S) injecting at 2375 psi, totalizer reading 960,062 BBLS. LAST MIT 5/6/2010

C1B(N) injecting at 1250, totalizer reading 628,834 BBLS. 2/26/2009

\*C1A(S) missing bradenhead pressure monitoring gage.

C1B(N) monitoring annular spaces.