

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

11/23/2012

Document Number:

669400284

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>216475</u>	<u>326426</u>		<u>LABOWSKIE, STEVE</u>

Operator Information:OGCC Operator Number: 19160 Name of Operator: CONOCO PHILLIPS COMPANYAddress: P O BOX 2197City: HOUSTONState: TXZip: 77252-**Contact Information:**

Contact Name	Phone	Email	Comment
McDaniel, Heather	(505) 326-9507	Heather.D.McDaniel@conoco-phillips.com	Regulatory Supervisor (Meridian Inspections)
Busse, Dollie	(505) 324-6104	Dollie.L.Busse@conocophillips.com	Staff Regulatory Technician

Compliance Summary:QtrQtr: SENW Sec: 29 Twp: 34N Range: 9W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/26/2011	200305086	PR	PR	S			N
12/07/2010	200286332	PR	PR	S			N
01/09/2010	200233131	PR	SI	S			N
03/09/2009	200205047	PR	PR	S			N
05/23/2008	200190354	PR	PR	S			N
11/14/2007	200121994	PR	PR	S			N
11/29/2006	200103122	PR	PR	S		P	N
08/18/2005	200077992	PR	PR	S		P	N
07/12/2004	200060842	PR	PR	S		P	N
07/15/2003	200043546	PR	PR	S		P	N
05/10/2002	200027750	PR	PR	S		P	N
01/16/2001	200015063	PR	PR	S		P	N
10/20/1999	500150695	PR	PR			P	N

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
216475	WELL	PR	02/01/2011	GW	067-08081	WILSON 34-9 29-1	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Inspector Name: LABOWSKIE, STEVE

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location				
-----------------	--	--	--	--

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access		abundant mature dead weeds along access, gone to seed	keep weeds from spreading onto cropland (2013 growth cycles), mowing is acceptable control measure	

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	below ground wellhead in field		
BATTERY	Satisfactory	equipment battery near highway		

Emergency Contact Number: (S/U/V) _____ Satisfactory _____ Corrective Date: _____

Comment: operator number on wellhead sign, only 911 at equipment battery

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
OTHER	Satisfactory	chain-link with visual barriers at equipment battery		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Horizontal Heater Treater	1				
Flow Line	1				
Gas Meter Run	1				
Ancillary equipment	1		AC equipment at wellhead		
Ancillary equipment	1		telemetry		
Horizontal Heated Separator	1				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 326426

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

Facility

Facility ID: 216475 Type: WELL API Number: 067-08081 Status: PR Insp. Status: PR

Producing Well

Comment:

Environmental**Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long

DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment: bare soil around wellhead, graveled pad at remote equipment battery

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Pass CM

CA CA Date

Pit, cellars, rat holes and other bores closed? Pass CM

CA CA Date

Guy line anchors removed? Pass CM

CA CA Date

Guy line anchors marked? CM

CA CA Date

1003b. Area no longer in use? In

Production areas stabilized ? Pass

Inspector Name: LABOWSKIE, STEVE

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established In

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					around equipment battery
Compaction	Pass					
Gravel	Pass					at equipment battery
		Other	Fail			rutts erosion in places on access

S/U/V: Unsatisfactory Corrective Date: 04/01/2013

Comment: lease road tire rutted in several places, with subsequent water erosion.

CA: smooth out/fill tire rutts, prevent water erosion