

FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
-------------------------------	--	--	-------------

Inspection Date: 08/22/2012

Document Number: 669300075

Overall Inspection: **Unsatisfactory**

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>NEIDEL, KRIS</u>
	<u>413061</u>	<u>414108</u>		

Operator Information:

OGCC Operator Number: 78110 Name of Operator: SWEPI LP

Address: 4582 S ULSTER ST PKWY #1400

City: DENVER State: CO Zip: 80237

Contact Information:

Contact Name	Phone	Email	Comment
	<u>(281) 544 4490</u>	<u>c.rosenbaum@shell.com</u>	

Compliance Summary:

QtrQtr: 2 Sec: 21 Twp: 5N Range: 91W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/06/2011	662300036	WO	TA	S			N
07/21/2011	200325362	PR	PR	U			Y
03/21/2011	200306173	PR	PR	U			Y

Inspector Comment:

location is along the side of county rd. well is not on production, there is no equipment on pad. wellhead has no tree or flowlines, well is night capped. Inspection is Unsatisfactory due to emergency number. well should have a sign at wellhead to identify as a hazard for the public to avoid .

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
413061	WELL	WO	02/10/2011	LO	081-07595	Castor Gulch 1-21 <input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>2</u>	Production Pits: _____
Condensate Tanks: <u>1</u>	Water Tanks: <u>3</u>	Separators: <u>2</u>	Electric Motors: _____
Gas or Diesel Mortors: <u>1</u>	Cavity Pumps: <u>2</u>	LACT Unit: _____	Pump Jacks: <u>1</u>
Electric Generators: <u>3</u>	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: <u>2</u>	VOC Combustor: _____	Oil Tanks: <u>2</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>1</u>	Fuel Tanks: <u>2</u>

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	no sign at wellhead.	Install sign to comply with rule 210.b.	01/09/2013

Emergency Contact Number: (S/U/V) Unsatisfactory Corrective Date: 01/09/2013

Inspector Name: NEIDEL, KRIS

Comment: emergency number not on sign.

Corrective Action: install emergency number.

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
LOCATION	Satisfactory	location is isolated from the public by large boulders, preventing parking on the pad.		

Venting:	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 414108

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Group	User	Comment	Date
OGLA	kubeczko	The drilling pit must be lined, or a closed loop system must be implemented during drilling. All cuttings generated during drilling with OBM must be kept in the lined drilling pit, or placed either in containers or on a lined/bermed portion of the well pad; prior to offsite disposal. The moisture content of any drill cuttings in a cuttings container or pile shall be as low as practicable to prevent accumulation of liquids greater than de minimis amounts.	08/29/2011

Comment: _____

CA: _____ Date: _____

Wildlife BMPs:

BMP Type	Comment
Storm Water/Erosion Control	<p>Stormwater Management Plans (SWMP) are in place to comply with both Colorado Department of Public Health and Environment (CDPHE) and Colorado Oil and Gas Conservation Commission (COGCC) stormwater discharge permits. The construction layout for Castor Gulch 1-21 details Best Management Practices (BMP) to be installed during initial construction. Note that BMPs may be removed, altered, or replaced with changing conditions in the field and the SWMP will be updated accordingly.</p> <p>The BMPs prescribed for the initial construction phase include, but are not limited to</p> <ul style="list-style-type: none"> • Construction diversion ditch • Sediment reservoirs • Check dams • Level spreaders • Stabilized construction entrance • Slash • Sediment trap • Wattle • Terrace • Secondary containment berms • Detention ponds
Material Handling and Spill Prevention	<p>Spill Prevention Control & Countermeasure Plans (SPCC) are in place to address material releases and to prescribe materials handling BMPs for the facility. "Good house-keeping" measures will be taken to ensure proper waste disposal.</p>
Wildlife	<p>See attached email from CDOW. CDOW recommendations and concerns – as agreed to by the operator, BLM, and CDOW.</p> <ol style="list-style-type: none"> 1) Check on status (active/not) of hawk nest site. – CDOW confirmed this and found the nest to be inactive. 2) Shell will make a good faith effort to finish drilling at this location by October 1 before the start of big game rifle hunting season. 3) CDOW will check on where to relocate the SLB-CDOW hunting access sign at the pad site where surface grading will be required. The sign should be replaced where it is highly visible. Shell will relocate the sign per CDOW direction. 4) Schedule post-construction - production well site visitations to between the hours of 10:00 a.m. and 3:00 p.m. and reduce well site visitations between December 1 and April 15 in elk winter range. 5) BLM stipulations from original lease permitting and COAs – timing stipulations for sharp-tailed grouse production should be applied. Per BLM. 6) Shell will contact the SLB regarding surface disturbance. 7) Weed management will be included as part of the interim and final reclamation.

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Inspector Name: NEIDEL, KRIS

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____
 Request LGD Attendance: _____
LGD Contact Information:
 Name: _____ Phone Number: _____ Agreed to Attend: _____
Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 413061 Type: WELL API Number: 081-07595 Status: WO Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 S/V: _____ CA Date: _____
 CA: _____
 Comment: _____

Environmental

Spills/Releases:
 Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:
 Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
 Land Use: RANGELAND
 Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? Pass Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____
 Comment:

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____
 Final Land Use: RANGELAND
 Reminder: _____
 Comment:
 Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____
 Comment:

Corrective Action: _____ Date _____

Overall Final Reclamation Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Sediment Traps	Pass					
Rip Rap	Pass					
Waddles	Pass					
Ditches	Pass					

S/U/V: Satisfactory Corrective Date: _____

Comment: access road is county rd. BMP are being maintained.

CA: _____