

FORM  
5

Rev  
02/08

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400347684

Date Received:

11/19/2012

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type  Final completion  Preliminary completion

1. OGCC Operator Number: 47120 4. Contact Name: JOEL MALEFYT  
 2. Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-6828  
 3. Address: P O BOX 173779 Fax: (720) 929-7828  
 City: DENVER State: CO Zip: 80217-

5. API Number 05-123-35258-00 6. County: WELD  
 7. Well Name: CAMP Well Number: 25N-30HZ  
 8. Location: QtrQtr: SWSE Section: 31 Township: 3N Range: 65W Meridian: 6  
 Footage at surface: Distance: 460 feet Direction: FSL Distance: 1357 feet Direction: FEL  
 As Drilled Latitude: 40.175943 As Drilled Longitude: -104.701710

GPS Data:

Date of Measurement: 08/13/2012 PDOP Reading: 1.4 GPS Instrument Operator's Name: Renee Doiron

\*\* If directional footage at Top of Prod. Zone Dist.: 862 feet. Direction: FSL Dist.: 2309 feet. Direction: FEL

Sec: 31 Twp: 3N Rng: 65W

\*\* If directional footage at Bottom Hole Dist.: 2076 feet. Direction: FSL Dist.: 2549 feet. Direction: FEL

Sec: 30 Twp: 3N Rng: 65W

9. Field Name: WATTENBERG 10. Field Number: 90750

11. Federal, Indian or State Lease Number: \_\_\_\_\_

12. Spud Date: (when the 1st bit hit the dirt) 04/07/2012 13. Date TD: 05/31/2012 14. Date Casing Set or D&A: 06/02/2012

15. Well Classification:

Dry  Oil  Gas/Coalbed  Disposal  Stratigraphic  Enhanced Recovery  Storage  Observation

16. Total Depth MD 14144 TVD\*\* 7156 17 Plug Back Total Depth MD 14127 TVD\*\* 7156

18. Elevations GR 4950 KB 4975

One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:

CBL; LWD; GRR, SGRR; MUD LOG

20. Casing, Liner and Cement:

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
SURF	13+1/2	9+5/8	36	0	853	620	25	853	CALC
1ST	8+3/4	7	26	0	7,556	835	570	7,556	CBL
1ST LINER	6+1/8	4+1/2	11.5	6453	14,129				CALC

**STAGE/TOP OUT/REMEDIAL CEMENT**

Cement work date: \_\_\_\_\_

Method used	String	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom

Details of work:

21. Formation log intervals and test zones:

**FORMATION LOG INTERVALS AND TEST ZONES**

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
SHARON SPRINGS	7,233		<input type="checkbox"/>	<input type="checkbox"/>	
NIOBRARA	7,373		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

\_\_\_\_\_

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: JOEL MALEFYT

Title: REGULATORY ANALYST Date: 11/19/2012 Email: JOEL.MALEFYT@ANADARKO.COM

**Attachment Check List**

Att Doc Num	Document Name	attached ?	
<b><u>Attachment Checklist</u></b>			
400347722	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
2113928	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
<b><u>Other Attachments</u></b>			
400347684	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400347726	DIRECTIONAL DATA	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

**General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Permit	Received and attached correct Directional Survey.	2/4/2013 1:11:22 PM
Permit	On hold. Directional Survey does not match directional data.	2/4/2013 11:46:35 AM

Total: 2 comment(s)