

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

02/04/2013

Document Number:

669300348

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>301557</u>	<u>335724</u>		<u>NEIDEL, KRIS</u>

Operator Information:OGCC Operator Number: 96850 Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVERState: COZip: 80202**Contact Information:****Compliance Summary:**QtrQtr: NWSE Sec: 24 Twp: 1S Range: 98W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
287633	WELL	PR	10/31/2006	GW	103-10937	FEDERAL RGU 33-24-198	<input checked="" type="checkbox"/>
301555	WELL	PR	10/24/2011	GW	103-11457	FEDERAL RGU 542-24-198	<input checked="" type="checkbox"/>
301556	WELL	PR	11/18/2011	GW	103-11458	FEDERAL RGU 342-24-198	<input checked="" type="checkbox"/>
301557	WELL	PR	10/24/2011	GW	103-11459	FEDERAL RGU 543-24-198	<input checked="" type="checkbox"/>
301558	WELL	PR	09/23/2011	GW	103-11460	FEDERAL RGU 343-24-198	<input checked="" type="checkbox"/>
301559	WELL	PR	05/05/2010	GW	103-11461	FEDERAL RGU 433-24-198	<input checked="" type="checkbox"/>
301560	WELL	PR	11/01/2010	GW	103-11462	FEDERAL RGU 532-24-198	<input checked="" type="checkbox"/>
301561	WELL	PR	10/14/2010	GW	103-11463	FEDERAL RGU 34-24-198	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>2</u>	Wells: <u>22</u>	Production Pits: _____
Condensate Tanks: <u>4</u>	Water Tanks: <u>4</u>	Separators: <u>2</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: <u>1</u>
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:					
Type	Area	Volume	Corrective action	CA Date	
<input type="checkbox"/> Multiple Spills and Releases?					

Fencing/:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	
TANK BATTERY	Satisfactory	Temporary fencing around tank battery and treater, there is a open excavation to burry flow lines.			
WELLHEAD	Satisfactory				

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Horizontal Heater Treater	4	Satisfactory			

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill			
Location ID: 335724			
Site Preparation:			
Lease Road Adeq.: _____	Pads: _____		
Corrective Action: _____	Soil Stockpile: _____		
	Date: _____ CDP Num.: _____		
Form 2A COAs:			
Group	User	Comment	Date
Agency	yokleyb	The moisture content of any drill cuttings in a cuttings pit, trench, or pile shall be as low as practicable to prevent accumulation of liquids greater than de minimis amounts. At the time of closure, the drill cuttings must also meet the applicable standards of table 910-1.	03/26/2010
Agency	yokleyb	Reserve pit must be lined.	03/26/2010
Agency	yokleyb	Location is in a sensitive area because of close proximity to surface water, therefore, operator must ensure 110 percent secondary containment for any volume of fluids contained at well site during drilling and completion operations. If fluids are conveyed via pipeline, operator must implement best management practices to contain any unintentional release of fluids.	03/26/2010
Agency	yokleyb	No portion of any pit that will be used to hold liquids shall be constructed on fill material, unless the pit and fill slope are designed and certified by a professional engineer, subject to review and approval by the director prior to construction of the pit. The construction and lining of the pit shall be supervised by a professional engineer or their agent. The entire base of the pit must be in cut.	03/26/2010
Agency	yokleyb	Operator must implement best management practices to contain any unintentional release of fluids.	03/26/2010
Comment: _____			
CA: _____			Date: _____

Wildlife BMPs:**Comment:** **CA:** **Date:** **Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: Date: Comments: Erosion BMPs: Other BMPs: **Comment:** **Staking:****On Site Inspection (305):**Surface Owner Contact Information:Name: Address: Phone Number: Cell Phone: Operator Rep. Contact Information:Landman Name: Phone Number: Date Onsite Request Received: Date of Rule 306 Consultation: Request LGD Attendance: LGD Contact Information:Name: Phone Number: Agreed to Attend: Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**Facility ID: 287633 Type: WELL API Number: 103-10937 Status: PR Insp. Status: PR**Producing Well**Comment: location is on final completions, flowlines are being buried.Facility ID: 301555 Type: WELL API Number: 103-11457 Status: PR Insp. Status: PR**Producing Well**Comment: location is on final completions, flowlines are being buried.Facility ID: 301556 Type: WELL API Number: 103-11458 Status: PR Insp. Status: PR**Producing Well**Comment: location is on final completions, flowlines are being buried.Facility ID: 301557 Type: WELL API Number: 103-11459 Status: PR Insp. Status: PR

Inspector Name: NEIDEL, KRIS

Producing Well

Comment: location is on final completions, flowlines are being buried.

Facility ID: 301558 Type: WELL API Number: 103-11460 Status: PR Insp. Status: PR

Producing Well

Comment: location is on final completions, flowlines are being buried.

Facility ID: 301559 Type: WELL API Number: 103-11461 Status: PR Insp. Status: PR

Producing Well

Comment: location is on final completions, flowlines are being buried.

Facility ID: 301560 Type: WELL API Number: 103-11462 Status: PR Insp. Status: PR

Producing Well

Comment: location is on final completions, flowlines are being buried.

Facility ID: 301561 Type: WELL API Number: 103-11463 Status: PR Insp. Status: PR

Producing Well

Comment: location is on final completions, flowlines are being buried.

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND

Comment:

1003a. Debris removed? CM
CA CA Date

Inspector Name: NEIDEL, KRIS

Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: Lots of ongoing work on location. Pits/trenches are in the process of being closed. Some open excavation to bury flow lines. snow on location.

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Berms	Pass					
Compaction	Pass	Compaction	Pass	MHSP	Pass	

S/U/V: Satisfactory Corrective Date: _____

Comment: Location is undergoing closing of pits/trenches. Inspector walked perimeter of location, no sediment is moving on/off of location. The day of inspection there was lots of melting snow so pad was wet and had some puddles, location should be reevaluated after construction is completed.

CA: _____