

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

03/15/2013

Document Number:

668200423

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|-------------|--------|-----------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection |
| | 209905 | 322216 | LEONARD, MIKE | <input type="checkbox"/> 2A Doc Num: _____ |

Operator Information:

| | | | |
|-----------------------|-------------|-------------------|---------------|
| OGCC Operator Number: | 44390 | Name of Operator: | JAVERNICK OIL |
| Address: | 3040 E MAIN | | |
| City: | CANON CITY | State: | CO |
| | | Zip: | 81212 |

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-----------------------------------|------------------------|------------|
| Mehennett, Tom | (719) 275-3040/ (505) 330-1328 | tbm3040@gmail.com | Regulatory |
| Javernick, Jim | (719) 275-3040 | javernick1@bresnan.net | Owner |

Compliance Summary:

| QtrQtr: | NWNE | Sec: | 2 | Twp: | 19S | Range: | 70W |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
| 06/04/2012 | 664000621 | PR | PR | U | P | | N |
| 01/07/2011 | 200292026 | PR | PR | S | | | N |
| 11/17/2006 | 200099435 | PR | PR | S | | P | N |
| 04/26/1995 | 500141715 | PR | PR | | | | |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------------------------------|
| 209905 | WELL | PR | 12/30/2005 | OW | 043-05180 | J J 1 | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|----------------------|-----------------------------|--------------------|---|------------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | Unsatisfactory | NO CAPACITY LABELS | Install sign to comply with rule 210.b. | 04/30/2013 |

Inspector Name: LEONARD, MIKE

| | | | |
|----------|----------------|--------------------------------------|---|
| WELLHEAD | Satisfactory | | |
| BATTERY | Unsatisfactory | BATTERY SIGN DOES NOT DESIGNATE JJ 2 | Install sign to comply with rule 210.b. |

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

Facilities:

☐ New Tank

Tank ID: _____

| Contents | # | Capacity | Type | SE GPS |
|-----------|---|----------|-----------|--------|
| CRUDE OIL | 2 | 300 BBLS | STEEL AST | , |

| | |
|--------|----------|
| S/U/V: | Comment: |
|--------|----------|

| | |
|--------------------|------------------|
| Corrective Action: | Corrective Date: |
|--------------------|------------------|

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|------------|---------------------|---------------------|-------------|
| Earth | Inadequate | Walls Sufficient | Base Sufficient | Inadequate |

| | | | |
|-------------------|--------------|-----------------|------------|
| Corrective Action | REPIAR BERMS | Corrective Date | 04/30/2013 |
|-------------------|--------------|-----------------|------------|

| | |
|---------|--|
| Comment | |
|---------|--|

Venting:

| | |
|--------|-------------------------------------|
| Yes/No | Comment |
| NO | NO ACTIVE VENTING DURING INSPECTION |

Flaring:

| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|------|-----------------------------|---------|-------------------|---------|
| | | | | |

Predrill

Location ID: 322216

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

| | | | |
|--------------|---------|------------|---------|
| Erosion BMPs | Present | Other BMPs | Present |
| | | | |

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 209905 Type: WELL API Number: 043-05180 Status: PR Insp. Status: PR

Producing Well

Comment: ON TIMER

Environmental**Spills/Releases:**

Inspector Name: LEONARD, MIKE

| | | |
|--|------------------------------|-------------------------------|
| Type of Spill: _____ | Description: _____ | Estimated Spill Volume: _____ |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | | |
| Corrective Action: _____ | | Date: _____ |
| Reportable: _____ | GPS: Lat _____ | Long _____ |
| Proximity to Surface Water: _____ | Depth to Ground Water: _____ | |

| | | | |
|------------------------|-------------------|-------------|------------|
| Water Well: | | Lat _____ | Long _____ |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ | |

Field Parameters:

Sample Location: _____

| |
|---|
| Emission Control Burner (ECB): _____ |
| Comment: _____ |
| Pilot: _____ Wildlife Protection Devices (fired vessels): _____ |

Reclamation - Storm Water - Pit

| | |
|--|---|
| Interim Reclamation: | |
| Date Interim Reclamation Started: _____ | Date Interim Reclamation Completed: _____ |
| Land Use: _____ | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| 1003a. | Debris removed? _____ CM _____ |
| | CA _____ CA Date _____ |
| | Waste Material Onsite? _____ CM _____ |
| | CA _____ CA Date _____ |
| | Unused or unneeded equipment onsite? _____ CM _____ |
| | CA _____ CA Date _____ |
| | Pit, cellars, rat holes and other bores closed? _____ CM _____ |
| | CA _____ CA Date _____ |
| | Guy line anchors removed? _____ CM _____ |
| | CA _____ CA Date _____ |
| | Guy line anchors marked? _____ CM _____ |
| | CA _____ CA Date _____ |
| 1003b. | Area no longer in use? _____ Production areas stabilized ? _____ |
| 1003c. | Compacted areas have been cross ripped? _____ |
| 1003d. | Drilling pit closed? _____ Subsidence over on drill pit? _____ |
| | Cuttings management: _____ |
| 1003e. | Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ |
| | Production areas have been stabilized? _____ Segregated soils have been replaced? _____ |
| RESTORATION AND REVEGETATION | |
| <u>Cropland</u> | |

Inspector Name: LEONARD, MIKE

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Compaction | Pass | | | |
| Compaction | Pass | Ditches | Pass | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____