

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

03/20/2013

Document Number:

670500624

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	428276	428267	MONTOYA, JOHN	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:OGCC Operator Number: 8960 Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLCAddress: 410 17TH STREET SUITE #1400City: DENVERState: COZip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Alan	661-444-0999	jaj@bonanzacrk.com	

Compliance Summary:

QtrQtr: <u>SESW</u>	Sec: <u>34</u>	Twp: <u>5N</u>	Range: <u>63W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/02/2012	661601683			U			N
07/02/2012	661601684			U			N

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
428262	WELL	XX	03/23/2012	LO	123-35291	North Platte 24-34	<input type="checkbox"/>
428270	WELL	PR	11/06/2012		123-35297	North Platte 33-34	<input type="checkbox"/>
428276	WELL	PR	11/06/2012		123-35300	North Platte 34-34	<input checked="" type="checkbox"/>
428282	WELL	XX	03/23/2012	LO	123-35304	North Platte N-34	<input type="checkbox"/>
428296	WELL	XX	03/23/2012	LO	123-35308	North Platte 23-34	<input type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>5</u>	Production Pits: _____
Condensate Tanks: <u>4</u>	Water Tanks: <u>2</u>	Separators: <u>3</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	no wellhead sign	Install sign to comply with rule 210.b.	04/20/2013

Inspector Name: MONTOYA, JOHN

Emergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory			

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	1	Satisfactory			

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 428267

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 428276 Type: WELL API Number: 123-35300 Status: PR Insp. Status: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: MONTOYA, JOHN

Comment: <input style="width: 700px;" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well:			
		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
Field Parameters:			
<input style="width: 300px;" type="text"/>			
Sample Location: <input style="width: 400px;" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

Reclamation - Storm Water - Pit

Interim Reclamation:			
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____	
Land Use: RANGELAND			
Comment: <input style="width: 750px;" type="text"/>			
1003a.	Debris removed? <u>Pass</u> CM _____		
	CA _____	CA Date _____	
	Waste Material Onsite? <u>Pass</u> CM _____		
	CA _____	CA Date _____	
	Unused or unneeded equipment onsite? <u>Pass</u> CM _____		
	CA _____	CA Date _____	
	Pit, cellars, rat holes and other bores closed? <u>Pass</u> CM _____		
	CA _____	CA Date _____	
	Guy line anchors removed? <u>Pass</u> CM _____		
	CA _____	CA Date _____	
	Guy line anchors marked? _____ CM _____		
	CA _____	CA Date _____	
1003b.	Area no longer in use? <u>Pass</u>		Production areas stabilized ? <u>Pass</u>
1003c.	Compacted areas have been cross ripped? _____		
1003d.	Drilling pit closed? <u>Pass</u>		Subsidence over on drill pit? <u>Pass</u>
	Cuttings management: _____		
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>Pass</u>		
	Production areas have been stabilized? <u>Pass</u>	Segregated soils have been replaced? <u>Pass</u>	
RESTORATION AND REVEGETATION			
<u>Cropland</u>			
	Top soil replaced _____	Recontoured _____	Perennial forage re-established _____

<u>Non-Cropland</u>			
Top soil replaced	<u>Pass</u>	Recontoured	<u>Pass</u>
		80% Revegetation	<u>Pass</u>
1003 f.	Weeds Noxious weeds?	<u>P</u>	
Comment:	<div></div>		
Overall Interim Reclamation	<u>Pass</u>		

Date Final Reclamation Started:	_____	Date Final Reclamation Completed:	_____
Final Land Use: RANGELAND _____			
Reminder: _____			
Comment:	_____		
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____		
Debris removed _____	No disturbance /Location never built _____		
Access Roads _____	Regraded _____	Contoured _____	Culverts removed _____
Gravel removed _____			
Location and associated production facilities reclaimed _____		Locations, facilities, roads, recontoured _____	
Compaction alleviation _____	Dust and erosion control _____		
Non cropland: Revegetated 80% _____		Cropland: perennial forage _____	
Weeds present _____	Subsidence _____		
Comment:	_____		
Corrective Action:	_____		Date _____
Overall Final Reclamation _____	Multi-Well Location	<input type="checkbox"/>	

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____