

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

03/25/2013

Document Number:

663800853

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

|                     |             |        |                 |                          |
|---------------------|-------------|--------|-----------------|--------------------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection       |
|                     | 211485      | 334572 | LONGWORTH, MIKE | <input type="checkbox"/> |
|                     |             |        | 2A Doc Num:     |                          |

**Operator Information:**OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

| Contact Name   | Phone        | Email                        | Comment |
|----------------|--------------|------------------------------|---------|
| Insp., General | 970-285-2665 | cogcc.inspections@encana.com |         |

**Compliance Summary:**QtrQtr: NESE Sec: 1 Twp: 7S Range: 94W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 12/21/2011 | 663800011 | PR         | PR          | S                            |          |                | N               |
| 08/09/2006 | 200101442 | PR         | PR          | S                            |          | P              | N               |
| 05/22/2003 | 200042632 | PR         | PR          | S                            |          | P              | N               |
| 10/10/2002 | 200034598 | PR         | PR          | S                            |          | P              | N               |
| 05/23/2002 | 200028529 | PR         | PR          | S                            |          | P              | N               |
| 03/27/2001 | 200015703 | PR         | PR          | S                            |          | P              | N               |

**Inspector Comment:****Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name             |                                     |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------------------------------|
| 211485      | WELL | PR     | 10/16/2003  | GW         | 045-07245 | SAVAGE 1-34               | <input checked="" type="checkbox"/> |
| 276681      | WELL | SI     | 10/10/2011  | GW         | 045-10511 | SAVAGE FEDERAL 1-9A (RI1) | <input checked="" type="checkbox"/> |
| 276682      | WELL | PR     | 07/23/2005  | GW         | 045-10510 | SAVAGE FEDERAL 1-9D (RI1) | <input checked="" type="checkbox"/> |

**Equipment:****Location Inventory**

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location**

|                    |                             |                  |                   |      |
|--------------------|-----------------------------|------------------|-------------------|------|
| <b>Lease Road:</b> |                             |                  |                   |      |
| Type               | Satisfactory/Unsatisfactory | comment          | Corrective Action | Date |
| Access             | Satisfactory                | Needs maintained |                   |      |

|                      |                             |         |                   |         |
|----------------------|-----------------------------|---------|-------------------|---------|
| <b>Signs/Marker:</b> |                             |         |                   |         |
| Type                 | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD             | Satisfactory                |         |                   |         |
| TANK LABELS/PLACARDS | Satisfactory                |         |                   |         |
| BATTERY              | Satisfactory                |         |                   |         |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

|                           |                             |                                   |                         |            |
|---------------------------|-----------------------------|-----------------------------------|-------------------------|------------|
| <b>Good Housekeeping:</b> |                             |                                   |                         |            |
| Type                      | Satisfactory/Unsatisfactory | Comment                           | Corrective Action       | CA Date    |
| UNUSED EQUIPMENT          | Unsatisfactory              | Frame for canopy(?) by separators | Remove unused equipment | 05/10/2013 |

|  |      |        |                   |         |
|--|------|--------|-------------------|---------|
| <b>Spills:</b>   |      |        |                   |         |
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

|                  |                             |                  |                   |         |
|------------------|-----------------------------|------------------|-------------------|---------|
| <b>Fencing/:</b> |                             |                  |                   |         |
| Type             | Satisfactory/Unsatisfactory | Comment          | Corrective Action | CA Date |
| LOCATION         | Satisfactory                |                  |                   |         |
| OTHER            | Satisfactory                | reclamation area |                   |         |

| <u>Equipment:</u>   |   |                             |                               |                   |         |
|---------------------|---|-----------------------------|-------------------------------|-------------------|---------|
| Type                | # | Satisfactory/Unsatisfactory | Comment                       | Corrective Action | CA Date |
| Ancillary equipment | 1 | Satisfactory                | Sand trap on Savage Fed. 1-9A |                   |         |

|                 |         |  |  |  |
|-----------------|---------|--|--|--|
| <b>Venting:</b> |         |  |  |  |
| Yes/No          | Comment |  |  |  |
|                 |         |  |  |  |

|                 |                             |         |                   |         |
|-----------------|-----------------------------|---------|-------------------|---------|
| <b>Flaring:</b> |                             |         |                   |         |
| Type            | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|                 |                             |         |                   |         |

**Predrill**

Location ID: 334572

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:**

|              |         |            |         |
|--------------|---------|------------|---------|
| Erosion BMPs | Present | Other BMPs | Present |
|              |         |            |         |

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 211485 Type: WELL API Number: 045-07245 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 276681 Type: WELL API Number: 045-10511 Status: SI Insp. Status: PR

**Producing Well**

Comment: Producing well

Facility ID: 276682 Type: WELL API Number: 045-10510 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing well

**Environmental****Spills/Releases:**

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

**Water Well:**

Lat Long

DWR Receipt Num: Owner Name: GPS :

**Field Parameters:**

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Fail CM

CA Remove unused equipment CA Date 05/10/2013

Pit, cellars, rat holes and other bores closed? Pass CM

CA CA Date

Guy line anchors removed? CM

CA CA Date

Guy line anchors marked? Pass CM

CA CA Date

Inspector Name: LONGWORTH, MIKE

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_

Segregated soils have been replaced? \_\_\_\_\_

#### RESTORATION AND REVEGETATION

##### Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

##### Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? P

Comment: \_\_\_\_\_

Overall Interim Reclamation In Process

#### **Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Multi-Well Location ☐

#### **Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Seeding          |                 | Gravel                  | Pass                  |               |                          |         |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |
| Ditches          | Pass            | Ditches                 | Fail                  |               |                          |         |
| Berms            | Pass            | Berms                   | Pass                  |               |                          |         |

S/U/V: Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

