










 Recovery/Test Trench
  Berm
  Staff Gauge
  Temporary Monitoring Well Point
 Approximate Location of Mini-Trench
 Boom
 Water Supply Well
 Other Fluid Level Gauging Location (Trench, Pothole, Temporary Boring)
 Parachute Creek
 Pipeline
 Monitoring Well

Notes:
1) Benzene results reported in $\mu\text{g/L}$ (micrograms per liter)
2) J = estimated value



Shaw Environmental, Inc.
(A CB&I Company)
9201 E. Dry Creek Rd.
Centennial, CO 80112