

Inspector Name: Peterson, Tom

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

05/31/2013

Document Number:

671100077

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|---------------|---------------|----------------------|--|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection |
| | <u>292415</u> | <u>310387</u> | <u>Peterson, Tom</u> | <input type="checkbox"/> 2A Doc Num: _____ |

Operator Information:OGCC Operator Number: 100322 Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVERState: COZip: 80202**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------|-----------------------------|------------|
| Pavelka, Linda | (303) 228-4064 | LPavelka@nobleenergyinc.com | Regulatory |

Compliance Summary:QtrQtr: NWSE Sec: 24 Twp: 7N Range: 67W**Inspector Comment:**Shared battery location with API#123-26332**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|----------------------------------|-------------------------------------|
| 292415 | WELL | PR | 10/13/2008 | OW | 123-26333 | CABALA RANCH & EXPLORATION 24-42 | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|----------------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| TANK LABELS/PLACARDS | Satisfactory | | | |
| WELLHEAD | Satisfactory | | | |
| BATTERY | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Inspector Name: Peterson, Tom

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

| Fencing/: | | | | |
|--------------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | | | |
| IGNITOR/COMBUST OR | Satisfactory | | | |

| Equipment: | | | | | |
|-----------------------------|---|-----------------------------|-------------------------|-------------------|---------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Emission Control Device | 1 | Satisfactory | | | |
| Plunger Lift | 1 | Satisfactory | | | |
| Bird Protectors | 2 | Satisfactory | | | |
| Horizontal Heated Separator | 1 | Satisfactory | N40.55654W 104.83225 | | |
| Flow Line | 1 | Satisfactory | | | |
| Gas Meter Run | 1 | Satisfactory | | | |

| | | | | | | |
|--------------------|--------------|-----------------------------------|----------------|---------------------|------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | | | |
| Contents | | # | Capacity | Type | SE GPS | |
| CRUDE OIL | | 1 | 300 BBLS | STEEL AST | , | |
| S/U/V: | Satisfactory | | Comment: | N40.55621W104.83220 | | |
| Corrective Action: | | | | | Corrective Date: | |

| Paint | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | _____ |
| Other (Capacity) | _____ |
| Other (Type) | _____ |

| Berms | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

Inspector Name: Peterson, Tom

| | | | | | |
|------------------------|-----------------------------|-----------------------------------|------------------------------|------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS | |
| PRODUCED WATER | 1 | <100 BBLS | PBV FIBERGLASS | , | |
| S/U/V: | Satisfactory | | Comment: N40.55621W104.83220 | | |
| Corrective Action: | | | | Corrective Date: | |
| <u>Paint</u> | | | | | |
| Condition | Adequate | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |
| Facilities: | | <input type="checkbox"/> New Tank | | Tank ID: _____ | |
| Contents | # | Capacity | Type | SE GPS | |
| PRODUCED WATER | 1 | <50 BBLS | BV CONCRETE | , | |
| S/U/V: | Satisfactory | | Comment: N40.55621W104.83220 | | |
| Corrective Action: | | | | Corrective Date: | |
| <u>Paint</u> | | | | | |
| Condition | Adequate | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |
| Venting: | | | | | |
| Yes/No | | Comment | | | |
| NO | | | | | |
| Flaring: | | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date | |
| | | | | | |

Predrill

Location ID: 310387

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 292415 Type: WELL API Number: 123-26333 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Environmental**Spills/Releases:**

Inspector Name: Peterson, Tom

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____ CA _____ CA Date _____
Waste Material Onsite? Pass CM _____ CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____ CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____ CA _____ CA Date _____
Guy line anchors removed? Pass CM _____ CA _____ CA Date _____
Guy line anchors marked? _____ CM _____ CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Inspector Name: Peterson, Tom

Top soil replaced Pass

Recontoured Pass

Perennial forage re-established Pass

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | SI | Pass | |

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____