

FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission <small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small>		DE	ET	OE	ES
--	---	--	----	----	----	----

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	232664	316759	NEIDEL, KRIS	2A Doc Num:	

Inspection Date:
05/24/2013

Document Number:
669300601

Overall Inspection:
Unsatisfactory

Operator Information:

OGCC Operator Number: 10409 Name of Operator: PEAKVIEW OPERATING COMPANY, LLC

Address: 216 16TH STREET, SUITE 1450

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Wise, Wayne		wwise@peakviewenergy.com	

Compliance Summary:

QtrQtr: SWNW Sec: 26 Twp: 6N Range: 87W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/09/2012	662300104			S			N
05/26/2011	1949087	PR	PR	U		F	Y
05/26/2011	200312722	PR	PR	U	I		Y
08/18/2010	200279892	PR	PR	U			Y
05/20/1999	500157966	PR	PR			F	N

Inspector Comment:

no sundry on file for continued venting of gas. Gas is being reported.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
232664	WELL	PR	10/16/2007	OW	107-06078	GRASSY CREEK COAL CO 3 <input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS	Satisfactory			

Inspector Name: NEIDEL, KRIS

BATTERY	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WEEDS	Unsatisfactory	around pad, in tank battery.	All locations, including wells and surface production facilities, shall be kept free of weeds; rubbish, and other waste material. Per rule 603.j	07/31/2013
TRASH	Unsatisfactory	trash cans at wellhead filled with what appears to be mostly historic cleanup of location. also a bucket filled with liquid oily wast	remove trash, do not store open buckets of oily waste.	07/31/2013

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

Multiple Spills and Releases?

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Deadman # & Marked	4	Satisfactory			
Pump Jack	1	Unsatisfactory	oily exhaust condensing on ground at end of pipe. old motor with leaky luber. casing gas	Evaluate practices to prevent further leaking, remediate oily soil.	07/31/2013

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
CRUDE OIL	3	300 BBLS	STEEL AST	,	
S/U/V:	Satisfactory	Comment:			
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No	Comment				
YES	exess gas being vented from AGTs				
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 316759

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 232664 Type: WELL API Number: 107-06078 Status: PR Insp. Status: PR

Producing Well

Comment: pumping

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
 Comment: _____
 Corrective Action: _____ Date: _____
 Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: _____ Lat _____ Long _____
 DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters: _____

Sample Location: _____

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____
 Comment: _____

- 1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
- Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
- Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
- Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
- Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
- Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Inspector Name: NEIDEL, KRIS

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? _____

Comment:

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					
Gravel	Pass					

S/U/V: Satisfactory Corrective Date: _____

Comment:

CA: