

Location Photos

Northerly

Date Photographed: 05-06-2013

Photographed By : C.Slaugh

NAD 83 - Decimal Degrees

Latitude : 39.430421

Longitude : 107.761524



Easterly

Date Photographed: 05-06-2013

Photographed By : C.Slaugh

NAD 83 - Decimal Degrees

Latitude : 39.430428

Longitude : 107.761602



**Tri State
Land Surveying, Inc.**

180 NORTH VERNAL AVE. VERNAL, UTAH 84078

P: (435) 781-2501
F: (435) 781-2518

DRAWN BY: D.C.R. REVISED:

DATE: 05-13-2013

ENCANA OIL & GAS (USA) INC.

Well Pad (K22W)

SEC. 22, T7S, R93W, 6th P.M.

Garfield County, CO.

COLOR PHOTOGRAPHS

SHEET

P2

Location Photos

Southerly

Date Photographed: 05-06-2013

Photographed By : C.Slaugh

NAD 83 - Decimal Degrees

Latitude : 39.430489

Longitude : 107.761529



Westerly

Date Photographed: 05-06-2013

Photographed By : C.Slaugh

NAD 83 - Decimal Degrees

Latitude : 39.430427

Longitude : 107.761498



Tri State
Land Surveying, Inc.
180 NORTH VERNAL AVE. VERNAL, UTAH 84078

P: (435) 781-2501
F: (435) 781-2518

ENCANA OIL & GAS (USA) INC.

Well Pad (K22W)
SEC. 22, T7S, R93W, 6th P.M.
Garfield County, CO.

DRAWN BY: DCR REVISED:
DATE: 05-13-2013

COLOR PHOTOGRAPHS

SHEET
P3