



**BAKER
HUGHES**

Report Printed on: FEB-06-13 10:04:33

CEMENT JOB REPORT



Shoe Test (Update Original Treatment Report for Primary Job)

Depth Drilled out of Shoe: 0 FT Target EMW: 0 LBS/GAL Actual EMW: 0 LBS/GAL
 Number of Times Tests Conducted: 0 Mud Weight When Test was Conducted: 0 LBS/GAL

Problems Before Job (I.E. Running Casing, Circulating Well, ETC)
 NONE

Problems During Job (I.E. Lost Returns, Equipment Failure, Bulk Delivery, Foaming, ETC)
 NONE

Problems After Job (I.E. Gas at Surface, Float Equipment Failed, ETC)
 NONE

PRESSURE/RATE DETAIL						EXPLANATION	
TIME HR:MIN.	PRESSURE - PSI		RATE BPM	Bbl. FLUID PUMPED	FLUID TYPE	SAFETY MEETING: BJ CREW <input checked="" type="checkbox"/> CO. REP. <input checked="" type="checkbox"/>	
	PIPE	ANNULUS				TEST LINES	3196 PSI
						CIRCULATING WELL - RIG	<input checked="" type="checkbox"/> BJ <input type="checkbox"/>
00:45	0	0	0	0	0	ARRIVE ON LOCATION (91 MILES)	
00:45	0	0	0	0	0	RIG PULLING DRILL PIPE	
02:00	0	0	0	0	0	RIG RUNNING CASING	
07:00	0	0	0	0	0	PRE RIG UP SAFETY MEETING	
07:35	0	0	0	0	0	PRE JOB MEETING	
07:52	3196	0	0	0	H2O	PRESSURE TEST PUMPS AND LINES	
07:55	29	0	6	15	H2O	FRESH WATER	
08:04	71	0	4	192	CMT	BATCH UP AND PUMP 860 SKS TYPE III+.08#/SACK STATIC FREE+1%CACL+.25#/SACK CELLO FLAKE@14.5#	
09:02	0	0	0	0	H2O	DROP PLUG	
09:03	498	0	7.2	70	H2O	START DISPLACEMENT	
09:14	598	0	6	30	H2O	SLOW RATE	
09:19	642	0	4.8	20	H2O	SLOW RATE	
09:23	725	0	3.6	17	H2O	SLOW RATE	
09:28	1389	0	0	0	H2O	BUMP PLUG @ 137 BBLS	
09:30	0	0	0	0	H2O	CHECK FLOATS	
09:40	0	0	0	0	0	POST JOB RIG DOWN SAFETY MEETING	
BUMPED PLUG <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	PSI TO BUMP PLUG 1387	TEST FLOAT EQUIP. <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	BBL.CMT RETURNS/ REVERSED 65	TOTAL BBL. PUMPED 344	PSI LEFT ON CSG 0	SPOT TOP OUT CEMENT <input checked="" type="checkbox"/> Y <input type="checkbox"/> N	Service Supervisor Signature: 