

<b>FORM INSP</b> Rev 05/11	<b>State of Colorado</b> <b>Oil and Gas Conservation Commission</b> 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
-------------------------------	--	--	----------------------

**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection	<input type="checkbox"/>
	417908	417910	QUINT, CRAIG	2A Doc Num:	

Inspection Date:  
08/06/2013

Document Number:  
668601200

Overall Inspection:  
Satisfactory

**Operator Information:**

OGCC Operator Number: 10234 Name of Operator: BAYHORSE PETROLEUM LLC

Address: 2558 E PORTSMOUTH AVE

City: SALT LAKE CITY State: UT Zip: 84121

**Contact Information:**

Contact Name	Phone	Email	Comment
Manikowski, Larry	801-942-5512	prmanski@gmail.com	Manager

**Compliance Summary:**

QtrQtr: SESW Sec: 21 Twp: 18S Range: 47W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/22/2012	663901555	PR	PR	S	P		N
05/03/2012	664000539	PR	PR	U	P		N
11/01/2011	664000085	PR	PR	S	F		N

**Inspector Comment:**

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
417908	WELL	PR	07/27/2010	OW	061-06845	TRADE WINDS 1-21	<input checked="" type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>3</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>1</u>	Electric Motors: _____
Gas or Diesel Mortors: <u>1</u>	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>1</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: <u>2</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	PARTIALLY ELEVATED DIRT ROAD ALONG RAILROAD TRACKS AND THOUGH FARM GROUND.		



BMP Type	Comment
PROPOSED BMPs	<p>BAYHORSE PETROLEUM, LLC</p> <p>2558 E. Portsmouth Ave.</p> <p>Salt Lake City, UT 84121 -5627</p> <p>(801) 913 -1640</p> <p><b>BEST MANAGEMENT PRACTICES</b></p> <p>Trade Winds 1 -21</p> <p>SESW of Section 21, T18S -R47W</p> <p>660' FSL and 1640' FWL</p> <p>Kiowa County, CO</p> <p>1) Bayhorse Petroleum will only use such land as necessary for said drilling, completion and production operations. The access road and well pad size will be kept to the minimum that is needed, without compromising safety.</p> <p>2) Bayhorse Petroleum will make every reasonable effort to minimize the impact of all equipment associated with this well. Dust disturbances will be kept at a minimum via access road and water sprinkling of the drill site as needed. We will ensure garbagelmud sacks, etc. be stored in a caged container during drilling operations, to prevent any materials from being blown onto the highway.</p> <p>3) Bayhorse Petroleum will minimize adverse visual contrast by utilizing an appropriate color selection for completion equipment to blend in with the background and natural surroundings.</p> <p>4) Bayhorse Petroleum will reclamate the surface as close to the original contour as possible. We will reshape the well location and access road as closely as possible to the original contour in the case of a dry hole. We will re- spread topsoil that has been stockpiled from the initial grading. We will re- establish native vegetation on the ingress/regress access area in the case of a dry hole. The drill site is on crop land.</p>

**Comment:**

**CA:**

**Date:** \_\_\_\_\_

**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

Corrective Action: _____		Date: _____	
Comments: Erosion BMPs: _____			
Other BMPs: _____			
<b>Comment:</b> _____			
<b>Staking:</b> _____			
<b>On Site Inspection (305):</b>			
<u>Surface Owner Contact Information:</u>			
Name: _____		Address: _____	
Phone Number: _____		Cell Phone: _____	
<u>Operator Rep. Contact Information:</u>			
Landman Name: _____		Phone Number: _____	
Date Onsite Request Received: _____		Date of Rule 306 Consultation: _____	
Request LGD Attendance: _____			
<u>LGD Contact Information:</u>			
Name: _____		Phone Number: _____	Agreed to Attend: _____
<u>Summary of Landowner Issues:</u>			
<u>Summary of Operator Response to Landowner Issues:</u>			
<u>Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:</u>			

Facility				
Facility ID: 417908	Type: WELL	API Number: 061-06845	Status: PR	Insp. Status: PR

Producing Well	
Comment:	PRODUCING

Environmental	
---------------	--

<b>Spills/Releases:</b>		
Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

<b>Water Well:</b>		
DWR Receipt Num: _____	Owner Name: _____	GPS : _____
		Lat _____
		Long _____

<b>Field Parameters:</b>
Sample Location: _____

Emission Control Burner (ECB): _____
--------------------------------------

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: DRY LAND

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: DRY LAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Inspector Name: QUINT, CRAIG

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
Gravel removed \_\_\_\_\_  
Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_  
Overall Final Reclamation Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	MHSP	Pass	

S/U/V: Satisfactory \_\_\_\_\_ Corrective Date: \_\_\_\_\_  
Comment: \_\_\_\_\_  
CA: \_\_\_\_\_