

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

08/28/2013

Document Number:

668601323

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Inspector Name:	On-Site Inspection
	<u>416957</u>	<u>416953</u>	<u>QUINT, CRAIG</u>	<input type="checkbox"/> 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10399 Name of Operator: NIGHTHAWK PRODUCTION LLCAddress: 1805 SHEA CENTER DR #290City: HIGHLANDS State: CO Zip: 80129**Contact Information:**

Contact Name	Phone	Email	Comment
Mayland, Harold	303-407-9604	haroldmayland@nighthawken ergy.com	operations manager
Wilson, Chuck	720-344-5155	chuckwilson@nighthawken y.com	CEO

Compliance Summary:QtrQtr: SWNE Sec: 2 Twp: 10S Range: 56W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/19/2012	663901275	TA	TA	V	F		Y
01/26/2012	664000331	TA	SI	U			N
10/05/2010	200283206	ID	TA	U			Y

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
416957	WELL	PR	09/04/2012	OW	073-06413	JOHN CRAIG 7-2	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>1</u>
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: <u>1</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	DIRT ROAD THROUGH PASTURE		

Inspector Name: QUINT, CRAIG

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	LEASE SIGN BY UNIT		
BATTERY	Satisfactory	LEASE SIGN BY BATTERY		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Facilities: <input type="checkbox"/> New Tank Tank ID: _____				
Contents	#	Capacity	Type	SE GPS
			CENTRALIZED BATTERY	39.208660,-103.631270
S/U/V:	Satisfactory	Comment:	CENTRAL BATTERY F/(JOHN CRAIG 6-2, 7-2)	
Corrective Action:				Corrective Date:

Paint

Condition	
-----------	--

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
Comment			

Venting:	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill				
Location ID: <u>416953</u>				
Site Preparation:				
Lease Road Adeq.: _____		Pads: _____	Soil Stockpile: _____	
Corrective Action: _____		Date: _____	CDP Num.: _____	
Form 2A COAs:				

Group	User	Comment	Date
Agency	kertr	Issued early for exigent circumstances because of change in geologic interpretation and rig schedule. Waivers and request attached to drilling permit.	04/30/2010

Comment:

CA: **Date:**

Wildlife BMPs:

BMP Type	Comment
PROPOSED BMPs	<p>RUNNING FOXES PETROLEUM INC.</p> <p>Reference COGCC Final Rome Amendment (December 17, 2008)</p> <p>1002. SITE PREPARATION:f. Stormwater Management A. thru F.</p> <p>RUNNING FOXES PETROLEUM, INC. (RFP) will implement the following procedures and practices to remove /reduce the possibility of</p> <p>discharged materials that may pollute water runoff from their field facilities, operations and well site locations. These procedures and practices, will minimize the potential of any discharge or spill that could potentially pollute surface water and any stormwater runoff.</p> <p>A Covering materials and activities:</p> <p>RFP will cover with tarps all containers /items that have the potential for material leakage. These items, whenever possible, will be kept in a central location within the operational area.</p> <p>B. Material handling. and spill prevention:</p> <p>RFP will use secondary containment methods, tarps, splash pans,</p> <p>or appropriate prevention items when transferring, pouring, or</p> <p>handling items that have the potential for spills. If items are on location for a period of time they will be on pallets off the ground.</p> <p>C.Erosion controls:</p> <p>RFP maintains and constructs well pads to minimize surface grade</p> <p>elevations. As season and weather changes; improvements to these</p> <p>well pads are adjusted accordingly. Roads, culverts, stream crossings and cut/fill slopes are prepared for runoff to be controlled and directed to desired locations.</p> <p>These controls will be constructed with the cooperation of the</p> <p>landowner to facilitate their use of the land. Interim Reclamation on well pads is accomplished as soon as possible to minimize the effects of erosion. Topsoil will be returned and reseeding will be completed.</p>

D. Self inspection, maintenance, and good housekeeping:

RFP has a pumper on location almost everyday to identify these

factors. Site improvement and inspection is a constant factor and

monitored with the anticipation of the season and the weather. As

potential contaminants are no longer needed at a set location they are removed and disposed of or stored in a more central secured monitored area. All vehicle washing is done off site.

E. SpHo response procedures:

RFP has a first response the standard dirt and shovel work; if the procedures described in B above don't initially contain the spill. This soil is removed from any surface water condition.

F. Vehicle tracking control procedures:

RFP attempts to design and maintain all roads to minimize any

rutting. All operational and access roads are on non -paved roads

with low potential of sediment contributing to stormwater

contamination.

7060B S. Tucson Way, Centennial, CO 80112.....(720) 889 -0510 Office

Comment:**CA:****Date:****Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Inspector Name: QUINT, CRAIG

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 416957 Type: WELL API Number: 073-06413 Status: PR Insp. Status: SI

Idle Well

Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____

S/V: _____ CA Date: _____

CA: _____

Comment: WELL IS SHUT IN AND BEING WORKED OVER TO CONVERT TO INJECTION WELL. CENTRAL BATTERY F/
(JOHN CRAIG 6-2, 7-2) 950' W @ 39.208660, -103.631270

Workover

Comment: CODELL RIG #5 ON LOCATION, DRILLING OUT CEMENT AFTER SQUEEZE JOB.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

Inspector Name: QUINT, CRAIG

1003a. Debris removed? Pass CM _____
CA _____ CA Date _____
Waste Material Onsite? Pass CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? Pass CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation In

1003 f. Weeds Noxious weeds? P

Comment: UNUSED AREAS OF THE LOCATION ARE COVERED WITH SOME GRASS AND WEEDS. CONTROL WEEDS.

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Inspector Name: QUINT, CRAIG

Corrective Action:

Date _____

Overall Final Reclamation

Multi-Well Location



Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Gravel	Pass	Compaction	Pass			

S/U/V: Satisfactory Corrective Date: _____

Comment: SW SIDE OF WELL PAD HAS AN AREA WITH STORM WATER EROSION. STORM WATER INSPECTOR FOR NIGHTHAWK WAS ON LOCATION.

CA: REPAIR AND INSTALL BMP's,